Plan Box #63	Date Job Name	3.2217 Slanci (PICES
App #(00)	Valuation 114 8/6	Heated SQ Feet 196
		Garage 576
Inspections for SED/SEA		= <u>1772</u>

Craw! Slab Мопо **Basement** Footing Footing Plum Under Slab Footing Foundation Foundation Ele. Under Slab Foundation Address Address Address Waterproofing **Open Floor** Slab Mono Slab Plum Under slab Rough In Rough In Rough In Address : Insulation Insulation insulation Slab Final Final Final Open Floor Rough In Insulation Finál

Foundation Survey. V

Envir. Health $\underline{\mathcal{NC}}\mathcal{N}'$

Other

Additions / Other

Footing	÷
Foundation	
Slab	•
Mono	
Open Floor	_
Rough In	
nsulation	
·I	