

ADDRESS . . : 115 SQUIRE ST
CONTRACTOR : WYNN CONSTRUCTION, INC.
OWNER . . . : LITTLE CROSS LLC
PARCEL . . . : 08-0653- - -0029- -23-
APPL NUMBER: 17-50041015 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : T/S: 03/23/2017 10:32 AM JBROCK ----
AVERY POND #23

SUBDIV: AVERY POND 32LOTS
PHONE : (919) 528-1347
PHONE :

75384877

STRUCTURE: 000 000 60X60 4BDR CRAWL W/ GARAGE & COV PORCH

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 4000000.00
SEPTIC - EXISTING? : NEW TANK
PROPOSED USE : SFD
WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
A814 01	<u>3/08/18</u>	<u>TI</u>	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 003098712 T/S: 03/07/2018 09:12 AM BPETRICH -----
B101 01	<u>3/08/18</u> <u>11</u>	<u>TI</u> <u>AP</u>	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 003098704 T/S: 03/07/2018 09:11 AM BPETRICH -----

COMMENTS AND NOTES

added in @ 9:29 Am

DAVID MILLER, PE

6300 Creedmoor Rd, STE 170#363

Raleigh, NC 27612

(919) 422-8932 (Office); DAVE@DMA-PA.COM

March 7, 2018

WYNN CONSTRUCTION

2550 CAPITAL DRIVE

SUITE 105

CREEDMOOR, NC 27522

Oliver Hudson

919-520-8406

e-mailed to: oliver@wynnhomes.com

RE: Engineering - Field Observation

Lot 23 Avery Pond Subdivision; Fuqua Varina, NC

Project No.:18DDM-0307A

To Whom It May Concern/Inspections Dept.:

The undersigned arrived on-site 3-7-18 to observe and test the foundation excavations for the planned residential structure. Based on the observations the reddish tan sandy silty clayey soils were firm when probed with the exception of some areas that were soft surface soils (approximately 1 to 3 feet below the planned footing bearing level) were firm when probed and should be backfilled with clean washed stone to the footing planned footing bearing level to provide adequate support of the planned loading conditions (2000 PSF bearing capacity).

Sincerely,

David Miller, PE

DEM/18DDM-0307A

