29212

HTE# 17-5-411232

Harnett County Department of Public Health

Improvement Permit

A building permit cannot be issued with only an Improvement Permit PROPERTY LOCATION: reserve Drive (nollins rd. Sa 1413) ISSUED TO: WINTERMORN LIONES FOR. SUBDIVISION The reserve LOT # 9 REPAIR □ EXPANSION □ NEW 🗔 Site Improvements required prior to Construction Authorization Issuance: Type of Structure: 482 70' x 66' SFD Proposed Wastewater System Type: 25% neduction 573. Projected Daily Flow: 425 GPD * Number of Occupants: & max Number of bedrooms: Basement Yes Pump Required: Tes No May be required based on final location and elevations of facilities Type of Water Supply:

Community Public Well Distance from well ________feet Permit valid for: Five years Permit conditions: ☐ No expiration Authorized State Agent:: Date: 08/28/2017 SEE ATTACHED SITE SKETCH The issuance of this permit by the Health Department in no way guarantees the issuance of other permits. The permit holder is responsible for checking with appropriate governing bodies in meeting their requirements. This site is subject to revocation if the site plan, plat, or the intended use changes. The Improvement Permit shall not be affected by a change in ownership of the site. This permit is subject to compliance with the provisions of the Laws and Rules for Sewage Treatment and Disposal and to conditions of this permit. Construction Authorization (Required for Building Permit) The construction and installation requirements of Rules .1950, .1952, .1954, .1955, .1956, .1957, .1958. and .1959 are incorporated by references into this permit and shall be met. Systems shall be installed in accordance with the attached system layout. ISSUED TO: Watermark Homes Inc. PROPERTY LOCATION: Meserve Of the Capilline and Sa 1413 SUBDIVISION The reserve LOT # 9 Basement? Yes Sasement Fixtures? Yes No Type of Wastewater System** Pump to 25% reaction 5,54em (Initial) Wastewater Flow: 480 GPD (See note below, if applicable 25% reduction 5756en (Repair) Exact length of each trench _______ feet Trench Spacing: ______ Feet Trenches shall be installed on contour at a Soil Cover: _______ inches Pump Tank Size _____ gallons Maximum Trench Depth of: ______ inches (Maximum soil cover shall not exceed (Trench bottoms shall be level to +/-1/4" 36" above the trench bottom) in all directions) Pump Requirements: _____ft. TDH vs. ____ GPM WATER LINES (INCLUDING IRRIGATION) MUST BE 10FT. FROM ANY PART OF SEPTIC SYSTEM OR REPAIR AREA. NO UTILITIES ALLOWED IN INITIAL OR REPAIR DRAIN FIELD AREA. **If applicable: I understand the system type specified is different from the type specified on the application. I accept the specifications of this permit. Owner/Legal Representative Signature: ___ This Construction Authorization is subject to revocation if the site plan, plat, or the intended use changes. The Construction Authorization shall not be transferred when there is a change in ownership of the site. This Construction Authorization is subject to compliance with the provisions of the Laws and Rules for Sewage Treatment and Disposal and to the conditions of this permit. SEE ATTACHED SITE SKETCH Authorized State Agent: Date: 08/28/2017 Construction Authorization Expiration Date: 08/28/2022 ANDREW CURRIN

Harnett County Department of Public Health Site Sketch

	PROPERTY LOCATON: Res	ene Drive (nonins	ns. 5/1413)
ISSUED TO: Watermark Hongs Inc.	SUBDIVISION	Reserve	LOT #
Authorized State Agent: ANDREW CO	MAN MAS	Date:	1017
	2281		
100 00 00 00 00 00 00 00 00 00 00 00 00	GARAGE PROPOSES OTHER LAY		571

Division of Environmental Health
On-Site Wastewater Section

Property ID: Lot #: File #: Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner: Same Applicant: Cum	bertund Homes, FAT.		
Address: Lot 9 The Reside	Date Evaluated: 04/18/17		
Proposed Facility: 3302 SEN	Design Flow (.1949): 360 CPD	Property Size:	
Location of Site: The The serve	Property Recorded: 165		
Water Supply: Publi	c□ Individual □ Well	☐ Spring	Other
Evaluation Method: Auger Boring	☐ Pit ☐ Cut		
Type of Wastewater:	age Industrial Process	☐ Mixed	

P R O F I .1940			SOIL MORPHOLOGY		OTHER PROFILE FACTORS				
E #	Position/ Slope %	Horizon Depth (In.)	.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
1	L <zi< td=""><td>0-8</td><td>66 LS</td><td>Vill wonessey</td><td></td><td></td><td></td><td></td><td></td></zi<>	0-8	66 LS	Vill wonessey					
		8-24	W SL	GR 358 527					PS
		24 - 40	BK SCL	F1 3 P 5/2	54R92 @ 38"	48			0.4
2	L<2%	0-8	SE 6 5	VEN NEN' Sign					
				M 359 36p					Rs
		20-40	BK SLL	FI SC SER	540 92 @ 36"	40			PS 0.4
3	L 22/2	0-8	SL , L5	VA WSONE X,					
		8-24	6R 5L	ra 558 54 p					Ps
		Z4-#0	BK SCL	F1 5 P SEP	542612@34"	40			0.4
4	L 2%	6-26	62 52	VA 451440					Q _C
	2	26-42	on su	FI 5 Phay	SYN92Q40"	42			P5 0,4
									,

Description	Initial System —	Repair System	Other Factors (.1946): Site Classification (.1948): Provisionally Son table
Available Space (.1945)			Evaluated By:
System Type(s)	2500 Res.	2510121.	Others Present: Andrew Curson, news
Site LTAR	0.4	4	Outers resent. Thorees Copper, wers