Department of Environment, Health and Natu "esources Division of Environmental Health On-Site Wastewater Section

Sheet:
Property II
Lot #:
File #:
Code:

## SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner:	Applicant:				
Address:	- 0 0-	Date Evaluated:	1		
Proposed Facility:	380m	Design Flow (.19	49): 360 <	Property Size:	
Location of Site:		Property Recorde	ed:		
Water Supply:	Pub	ic Individual	☐ Well	☐ Spring	Other
Evaluation Metho	d: Auger Boring	☐ Pit		Cut	
Type of Wastewar	ter: Sev	age Ind	ustrial Process	☐ Mixed	

P R O F I .1940 L Landscar E Position/ Slope %		Horizon Depth (In.)	SOIL MORPHOLOGY		OTHER PROFILE FACTORS				
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
)	L5 2-5	036	G L5	you so were					
-		36-46	CSL	golsu MU					5.6
2		034	GSL	V-2 NS/NP					
		34-71	58× SCL	VEZ 35/108					15

Description	Initial	Repair System	Other Factors (.1946):
	System		Site Classification (.1948):
Available Space (.1945)	V		Evaluated By: OX
System Type(s)	25%	200	Others Present:
Site LTAR	,5	.5	

- NO STERS NEEDED

COMMENTS:

LANDSCAPE POSITIONS	<u>GROUP</u>	TEXTURES	. <u>1955 LTAR</u>	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	П	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	Ш	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

IV SIC-SILTY CLAY 0.4 - 0.1 C-CLAY

SC-SANDY CLAY

STRUCTURE SG-SINGLE GRAIN M- MASSIVE CR-CRUMB **GR-GRANULAR** SBK-SUBANGULAR BLOCKY ABK-ANGULAR BLOCKY PL-PLATY

PR-PRISMATIC

MINERALOGY SLIGHTLY EXPANSIVE

**EXPANSIVE** 

Show profile locations and other site features (dimensions, references or benchmark, and North)



