Plan Box # ES	Date/ Date/ し/2.1/17 Job Nameンプ H		
App # 41429	Valuation 196320	SQ Feet <u>2045</u> Garage <u>395</u> = 2448	

## Inspections for SFD/SFA

.

.

Crawl	Slab	Mono	Basement
Footing	Footing	Plum Under Slab	Footing
Foundation	Foundation	Ele. Under Slab	Foundation
Address	Address	Address	Waterproofing
Open Floor	Slab	Mono Slab	Plum Under slab
Rough in	Rough In	Rough In	Address
nsulation	Insulation	Insulation	Slab
inal	Final	Final	Open Floor
			Rough in
			Insulation
			Final
oundation Sur	vey <u> </u>	vir. Health	Other
oundation Sur	vey <u> </u>	vir. Health	Other
l <u>ditions / Oth</u> o oting undation b	<u>er</u>	vir. Health	Other
lditions / Othe oting undation	<u>er</u>	vir. Health	Other
l <u>ditions / Oth</u> o oting undation b	<u>er</u>	vir. Health	Other
lditions / Othe oting undation b	<u>er</u>	vir. Health	Other
lditions / Othe oting undation b bno en Floor	<u>er</u>	vir. Health	Other