
ADDRESS : 179 MILLER RD SUBDIV:
 CONTRACTOR : STE GENERAL CONTRACTORS, LLC PHONE : (910) 891-5465
 OWNER : MELLOTT RANDY A & PHYLLIS A PHONE : (910) 892-2102
 PARCEL : 02-1528- - -0135- - -
 APPL NUMBER: 17-50041519 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : TAKE HWY.421 TO BUIES CRREK - TAKE HWY
 27 THRU COATS TO HODGES CHAPEL RD -
 TAKE RIGHT ON HODGES CHAPEL RD TO
 NEIGHBORS RD - TAKE RIGHT THEN TAKE
 LEFT ON MILLER RD AND PROPERTY WILL BE
 1000' ON LEFT
 CALLED IN PREMISE# 12/29/17..LLUCAS

STRUCTURE: 000 000 65X65 4BDR W/GARAGE W/DECK CRAWL

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 4.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW SEPTIC WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	12/13/17	DT	R*BLDG FOOTING / TEMP SVC POLE VRU #: 003065901
	12/13/17	AP	T/S: 12/13/2017 01:52 PM DETAYLOR -----
A814 01	1/11/18	SB	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 003074689
	1/12/18	AP	179 MILLER RD BENSON 27504
			T/S: 01/12/2018 09:13 AM SBENNETT -----
B103 01	1/11/18	DT	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 003074697
	1/11/18	DA	T/S: 01/10/2018 10:11 AM LLUCAS -----
			T/S: 01/11/2018 03:34 PM DETAYLOR -----
			Foundation incomplete
B103 02	1/16/18	DT	R*BLDG FOUND & TEMP SVC POLE VRU #: 003076023
	1/16/18	AP	T/S: 01/16/2018 04:01 PM DETAYLOR -----
B105 01	1/25/18	BS	R*OPEN FLOOR VRU #: 003080033
	1/25/18	AP	T/S: January 25, 2018 02:48 PM BSUTTON -----
R425 01	2/28/18	DT	FOUR TRADE ROUGH IN VRU #: 003094886
	2/28/18	DA	T/S: 02/28/2018 03:32 PM BPETRICH -----
R425 02	3/02/18	TI	FOUR TRADE ROUGH IN VRU #: 003096447
	<u>3/2/18</u>	<u>AP DT</u>	

COMMENTS AND NOTES

AA TAKLA ENGINEERING, PLLC

Consulting. Design. Efficiency.



ANDY A. TAKLA, EI
919-423-0470
ANDYTAKLA@TAKLAENGR.COM
Cert. #A-29014

ATEF A. TAKLA, PE
919-358-1758
ATEFTAKLA@TAKLAENGR.COM
Lic. #14578

ALFRED A. TAKLA, EI
919-332-7903
ALFREDTAKLA@TAKLAENGR.COM
Cert. #A-20939

NC Firm License No. P-1446
PO Box 71298 Durham NC 27722

FIELD REPORT

Date:

2/19/18

Project:

179 Miller RD

Location:


Benson, NC

Company:

STE General Contractor

Care of:

C/O Shane McLeod



AS REQUESTED, A. TAKLA VISITED THE PROPERTY and PERFORMED 3RD Party Inspection for THE Framing of the above referenced property and found it adequate, meets approved Plans, Complies with NCSRC-2012 Edition. Notes Garage's Portal Frame as-Installed is acceptable provided that The 5/8" Threaded Rod nuts be tightened

Limitations of Inspection Services provided are in accordance with the standard of practice for structural engineering and within the limits imposed by scope, schedule and budget. The determinations contained in this report are based on conditions observed at the time of the evaluation. No guarantees or warranties, expressed or implied, under this Agreement or otherwise, shall be construed in connection with services provided. Sequencing, and means and methods of construction are considered beyond the scope of this report.