

ADDRESS : 94 HEATHERWOOD DR
CONTRACTOR : GML DEVELOPMENT INC
OWNER : MCKEE HOMES LLC
PARCEL : 03-9589-01- -1021- -26-
APPL NUMBER: 17-50041624 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : T/S: 06/14/2017 10:48 AM JBROCK ----
OAKMONT #193 - 94 HEATHERWOOD DR


STRUCTURE: 000 000 36.4X51.6 3BDR MONO W/ GARAGE
FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3000000.00
SEPTIC - EXISTING? : NEW TANK
PROPOSED USE : SFD
WATER SUPPLY : GARAGE

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
P309 01	8/10/17	JLP	R*PLUMB UNDER SLAB VRU #: 003010279
	8/10/17	AP	T/S: 08/10/2017 02:18 PM JPERRY
A814 01	8/14/17	SB	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 003011855
	8/14/17	AP	94 HEATHERWOOD DR LILLINGTON 2754 94 HEATHERWOOD DR LILLINGTON 27546 T/S: 08/14/2017 11:14 AM SBENNETT
B114 01	8/14/17	JH	R*BLDG MONO SLAB/TEMP SVC POLE TIME: 17:00 VRU #: 003011939
	8/14/17	CA	T/S: 08/14/2017 08:22 AM JBROCK NOT READY
B114 02	8/16/17	TI	R*BLDG MONO SLAB/TEMP SVC POLE TIME: 17:00 VRU #: 003012804
	8-16-17	AP JV	T/S: 08/15/2017 10:49 AM JBROCK

per Engineer letter

COMMENTS AND NOTES



FIELD REPORT

PROJECT NAME: <u>Colony</u>	PROJECT #: <u>01-11-15</u>
PROJECT LOCATION: <u>Littlington, VA</u>	SUMMIT REPRESENTATIVE: <u>M. Gibbs</u>
DATE: <u>09-14-17</u>	PRESENT AT SITE:
CLIENT/CONTRACTOR: <u>W. H. H. Co.</u>	TRIPS:
WORK PERFORMED: <u>HA-DCP</u>	TOTAL TIME:

As requested Summit rep reported to the above referenced site to evaluate near surface foundation bearing materials for the proposed Lot: 193

Address: n/a

Permit #: n/a

Our testing and observation indicate that the soils listed ~~are not~~ suitable for the minimum allowed bearing capacity of 2000 psf

Please review order of test soils to be tested
 Contact Summit for reschedule:
6-12" marked by orange paint

SURVEY CONTROL: _____

RETURN VISIT REQUIRED: YES NO
 Summit observed repairs
 SIGNED (CLIENT/CONTRACTOR IF REQUIRED)

DATE TIME RETURN: _____
 SIGNED (SUMMIT) M. Gibbs
 SIGNED (CLIENT/CONTRACTOR IF REQUIRED)