

Sheet:  
 Property ID:  
 Lot #:  
 File #:  
 Code:

**SOIL/SITE EVALUATION**  
 for ON-SITE WASTEWATER SYSTEM

Owner: *Beverly*  
 Applicant: *Signature Homes Bldg*  
 Address: *Lot 2 Ebenezer Church Rd*  
 Date Evaluated: *06/29/17*  
 Proposed Facility: *4BR SFD*  
 Design Flow (.1949): *480 GPD*  
 Location of Site: *480 GPD*  
 Property Recorded: *Yes*  
 Water Supply:  Public  Individual  Well  
 Evaluation Method:  Auger Boring  Pit  Cut  
 Type of Wastewater:  Sewage  Industrial Process

Property Size: *5.03 AC*  
 Spring  Other  
 Mixed

P R O F I L E #	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				Profile Class & LTAR
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	
1	L 4%	0-38	GR SL	FR SSP SP					PS 0.4
		38-48	BK SCL	FI SP SP			48		
2	L 4%	0-40	GR SL	FR SSP SP					PS 0.4
		40-44	GR LS	FR SSP SP					
		44-48	BK SCL	FI SP SP			48		
3	L 4%	0-34	GR SL	FR SSP SP					PS 0.4
		34-48	BK SCL	FI SP SP			48		
		0-38	GR SL	FR SSP SP					
		34-48	BK SCL	FI SP SP	7.5YR7.1 @ 44"		48		

Description	Initial System	Repair System	Other Factors (.1946): Site Classification (.1948): <i>Provisionally Suitable</i> Evaluated By: <i>Andrew Curria, AETS</i> Others Present:
Available Space (.1945)			
System Type(s)	<i>25% red</i>	<i>25% red</i>	
Site LTAR	<i>0.4</i>	<i>0.4</i>	