

**COUNTY OF HARNETT**  
**Building Inspections Department**  
**Planning Services**

**Certificate of Compliance:** \_\_\_\_\_ **Occupancy:**

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: Residential  
Name: Stone Karen S. + Robert

**Permit Numbers**  
Building: \_\_\_\_\_  
Electrical: \_\_\_\_\_  
Insulation: \_\_\_\_\_  
Plumbing: \_\_\_\_\_  
Mechanical: \_\_\_\_\_  
MFG Home: \_\_\_\_\_  
50041842

Address: 11441 NC 27W

Date: 5/9/18 Building Official: [Signature]

-----

ADDRESS . . : 11441 NC 27 W SUBDIV:  
 CONTRACTOR : BRAD D CUMMINGS CONSTRUCTION PHONE : (910) 814-3232  
 OWNER . . : STONE KAREN C & ROBERT W II PHONE :  
 PARCEL . . : 03-0507- - -0038- -02-  
 APPL NUMBER: 17-50041842 CP NEW RESIDENTIAL (SFD)  
 DIRECTIONS : T/S: 07/14/2017 11:33 AM JBROCK ----  
 HWY 27 W OUT OF LILLINGTON PASS WHHS &  
 WHMS ON L JOB SIT ON L LOOK FOR SIGN  
 FOLLOW PATH  
 T/S: 11/29/2017 09:19 AM JBROCK ----  
 premise # 46284801  
 CALLED IN PREMISE# 12/18/17..LL 2:56PM  
 \*\*NEW PREMISE#42226070  
 CALLED IN PREMISE# 12/20/17..LL 9:21AM

-----  
**STRUCTURE: 000 000 57X54 3BDR 3BA CRAWL W/ GARAGE & DECK**

FLOOD ZONE . . . . : FLOOD ZONE X  
 # BEDROOMS . . . . . : 3000000.00 PROPOSED USE . . . . . : SFD  
 SEPTIC - EXISTING? . . . . : NEW TANK WATER SUPPLY . . . . . : COUNTY

-----  
**PERMIT: CPSF 00 CP \* SFD**

| TYP/SQ  | REQUESTED<br>COMPLETED | INSP<br>RESULT | DESCRIPTION<br>RESULTS/COMMENTS  |
|---------|------------------------|----------------|--|
| B101 01 | 9/06/17<br>9/06/17     | TSG<br>AP      | R*BLDG FOOTING / TEMP SVC POLE VRU #: 003021201<br>With the impending rain for tomorrow, please schedule for as early as possible. Thank you - Brad - 919.770.4693   |
| B103 01 | 9/20/17<br>9/20/17     | TSG<br>AP      | R*BLDG FOUND & TEMP SVC POLE VRU #: 003026986<br>1-MICRO WAVE VENT NOT COMPLETE 2-REPAIR HOLE IN DRYWALL<br>3-RAISE SEWER CLEAN OUT 4-APPEARS TO BE A LEAK ON TOP OF THE WATER HEATER.   |
| A814 01 | 9/20/17<br>9/20/17     | SB<br>AP       | ADDRESS CONFIRMATION TIME: 17:00 VRU #: 003026978<br>11441 NC 27 W LILLINGTON 27546<br>T/S: 09/20/2017 10:18 AM SBENNETT -----   |
| B105 01 | 9/26/17<br>9/26/17     | TSG<br>AP      | R*OPEN FLOOR VRU #: 003029758  |
| E207 01 | 11/28/17<br>11/28/17   | KS<br>AP       | R*ELEC TEMP SERVICE POLE TIME: 17:00 VRU #: 003058328<br>T/S: 11/27/2017 01:49 PM LLUCAS -----<br>T/S: 11/28/2017 12:42 PM KSLATTUM -----<br>Need premis number for duke power   |
| R425 01 | 11/28/17<br>11/28/17   | KS<br>DA       | FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 003058294<br>T/S: 11/27/2017 01:48 PM LLUCAS -----<br>T/S: 11/28/2017 12:43 PM KSLATTUM -----<br>1. Need air barrier beneath stairs. 2. Water distribution not 100 psi. 3. Fire block 3 inch hoe next to 3 inch pip in bottom plate of buddy bath. 4. Need baffles installed 5. Need 2 foot wakway to upstairs air handler. 6. Need to seal around foundation sleeve for drain. OK to side. |
| R425 02 | 12/06/17<br>12/06/17   | JH<br>AP       | FOUR TRADE ROUGH IN VRU #: 003061686<br>-----  |
| I129 01 | 12/13/17<br>12/13/17   | TSG<br>AP      | R*INSULATION INSPECTION VRU #: 003065851<br>T/S: 12/13/2017 11:03 AM SGUY -----  |
| H824 01 | 3/09/18<br>3/09/18     | AC<br>AP       | ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 003100716<br>T/S: 03/12/2018 11:29 AM KHINSON -----<br>T/S: 03/12/2018 11:29 AM KHINSON -----  |