

Lot 125

42147

DAVID MILLER, PE

6300 Creedmoor Rd, STE 170#363

Raleigh, NC 27612

(919) 422-8932 (Office); DAVE@DMA-PA.COM

November 3, 2017

WYNN CONSTRUCTION

2550 CAPITAL DRIVE

SUITE 105

CREEDMOOR, NC 27522

E-mailed to: jason@wynnhomes.com ; keith@wynnconstruct.com ; cdunham@wynnhomes.com

Craig Dunham 910-988-5691

RE: Engineering - Foundation
Lot 125 Anderson Creek Crossing
Lillington, NC
Project No.: 17DDM-1103B


To whom it may concern/ Inspections Dept.:

Representatives of the undersigned's arrived on-site 11-3-17 to observe and test the in-place fill conditions for the above referenced site. Based on the testing (Per ATM Special publication 399) the bearing materials (Tan silty to sandy clay to clayey sand (Unified Soil Classification System - CL/SC)) were adequate to support the planned structure. Based on the observations and testing the bearing soils for the footings will provide adequate support.

Sincerely,

David Miller, PE

DEM/17DDM-1103B



ADDRESS : 60 WILDLIFE BRIDGE CT SUBDIV: ACC CROSSING PH8 SECT2A 21LTS
CONTRACTOR : WYNN CONSTRUCTION, INC. PHONE : (919) 528-1347
OWNER : ANDERSON CREEK PARTNERS LP PHONE :
PARCEL : 01-0535-26- -0100- -17-
APPL NUMBER: 17-50042167 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : T/S: 08/29/2017 03:44 PM JBROCK ----
ANDERSON CREEK CROSSING #125

STRUCTURE: 000 000 39X60.5 4BDR MONO W/ GARAGE & COV B POR

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 4000000.00 PROPOSED USE : SFD
SEPTIC - EXISTING? : SEWER WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
A814 01	10/27/17 10/26/17	SB AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 003044906 60 WILDLIFE BRIDGE CT SPRING LAKE 28390 T/S: 10/26/2017 09:39 AM SBENNETT -----
P309 01	10/27/17 10/27/17	JH AP	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 003044914 T/S: 10/25/2017 04:10 PM LLUCAS -----
E207 01	11/03/17 11/03/17	TSG AP	R*ELEC TEMP SERVICE POLE TIME: 17:00 VRU #: 003048964 T/S: 11/02/2017 01:31 PM BPETRICH ----- T/S: 11/03/2017 03:04 PM LLUCAS -----
M305 01	11/03/17 11/03/17	TSG AP	R*PLUMB SEWER CONNECTION TIME: 17:00 VRU #: 003048881 T/S: 11/02/2017 01:08 PM BPETRICH ----- T/S: 11/03/2017 03:04 PM LLUCAS -----
P307 01	11/03/17 11/03/17	TSG AP	R*PLUMB WATER CONNECTION TIME: 17:00 VRU #: 003048873 T/S: 11/02/2017 01:08 PM BPETRICH ----- T/S: 11/03/2017 03:04 PM LLUCAS -----
B114 01	11/07/17 11/07/17	JB CA	R*BLDG MONO SLAB/TEMP SVC POLE TIME: 17:00 VRU #: 003050085 T/S: 11/06/2017 11:57 AM DJOHNSON ----- T/S: 11/07/2017 08:10 AM JBROCK ----- ca per craig
B114 02	11/09/17 11/09/17	BP CA	R*BLDG MONO SLAB/TEMP SVC POLE TIME: 17:00 VRU #: 003051323 T/S: 11/08/2017 01:07 PM JBROCK ----- T/S: 11/09/2017 11:24 AM BPETRICH ----- CANCELLED PER CRAIG
B114 03	11/15/17 <u>11-15-17</u>	TI <i>DA JH</i>	R*BLDG MONO SLAB/TEMP SVC POLE TIME: 17:00 VRU #: 003052834 T/S: 11/14/2017 09:23 AM LLUCAS -----
P309 02	11/15/17 <u>11-15-17</u>	TI <i>AP JH</i>	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 003052826 T/S: 11/14/2017 09:23 AM LLUCAS -----

----- COMMENTS AND NOTES -----

