

FIELD REPORT

on-site to observe materials / conditions
 at existing / exposed foundation excavations
 Foundation was overexcavated (up to 4' in areas)
 down to firm residual soils. The in-situ
 soils were qualitatively probed and subjected
 to static cone Penetrometer (scpt) testings.
 Based on our observations, analysis, and results
 of our field testing program, the in-situ
 soils were noted as adequate to support
 the anticipated loading conditions (2000 psf.).

* See enclosed letter to follow



TYNDALL
 ENGINEERING & DESIGN, P.A.

T 919-773-1200 F 919-773-9658
 69 Shipwash Drive Garner North Carolina 27529
 www.tyndallengineering.com

JOB Permit No. 17-50042202
 LOCATION Harnett Co.
 CALCULATED BY LWS DATE 12-13-17
 SHEET NO. _____ OF _____
 SCALE _____

VIOLATION NOTICE

DO NOT REMOVE!

Harnett County Inspection Department

108 East Front Street • P.O. Box 65

Lillington, NC 27546

Phone: (910) 893-7525 Ext. 1 • Fax: (910) 893-2793

Job Name: NC CUSTOM HOMES Date: 12/14/17

Address: 1460 OLIVE BRANCH RD.

Lot No.: — Permit No.: 17-SD042202

(Check Box for Violation)

- | | | | | | | | |
|-------------------------------------|--------------------------|--------------------------|--------------------------|--------------------------|--------------------------|--------------------------|--------------------------|
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| Footing | Foundation | Bldg. | Elec. | Plumb. | Mech. | Insul. | Floor Fram. |
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| Floor Slab | MFG. Home | Modular | Damp/Water Proof. | Structural | Wall Sheath. | Other | |

Violations Found: ① Excavation of Footing OK pending sealed soils report.

Code Enforcement Official

Signature: [Signature] Date: 12/14/17

It is unlawful for any subcontractor, general contractor, or owner to cover or cause to be covered any part of the work with flooring, sheetrock, earth or other material until the proper inspector had ample time to approve the installation