



A A TAKLA ENGINEERING, PLLC

Consulting. Design. Efficiency.

ANDY A. TAKLA, EI
919-423-0470
ANDYTAKLA@TAKLAENGR.COM
Cert. #A-29014

ATEF A. TAKLA, PE
919-358-1758
ATEFTAKLA@TAKLAENGR.COM
Lic. #14578

ALFRED A. TAKLA, EI
919-332-7903
ALFREDTAKLA@TAKLAENGR.COM
Cert. #A-20939

NC Firm License No. P-1446
PO Box 71298 Durham NC 27722

FIELD REPORT

Date: 4/6/18
Project: 14 Brookview CT
Location: Angier NC
Company: Lamco Custom Builders & Small. Con.
Care of: Lamco (Tony Toro)
(919) 935-9282



AS REQUESTED, A. TAKLA VISITED THE SITE and evaluated the following items at the above referenced property.

(A) structural fill (#57 stone) under House's slab (and Garage) was evaluated and found adequate to carry the slab and its loads

No repairs are needed.

Limitations of Inspection Services provided are in accordance with the standard of practice for structural engineering and within the limits imposed by scope, schedule and budget. The determinations contained in this report are based on conditions observed at the time of the evaluation. No guarantees or warranties, expressed or implied, under this Agreement or otherwise, shall be construed in connection with services provided. Sequencing, and means and methods of construction are considered beyond the scope of this report.