

ADDRESS : 955 RAYNOR-MCLAMB RD SUBDIV:
 CONTRACTOR : RED DOOR HOMES OF FAYETTEVILLE PHONE : (910) 672-8900
 OWNER : VLS REAL ESTATE LLC PHONE :
 PARCEL : 12-0556- - -0097- -07-
 APPL NUMBER: 17-50042462 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 10/04/2017 04:07 PM BPETRICH --
 T/S: 12/15/2017 01:55 PM LLUCAS ----

STRUCTURE: 000 000 52X59 4BD 2BA SLAB W/GARAGE

FLOOD ZONE : FLOOD ZONE X
 # BATHS : 2 # BEDROOMS : 4.00
 PROPOSED USE : SFD SEPTIC - EXISTING? : NEW TANK
 WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
A814 01	12/14/17 12/13/17	SB AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 003066156 955 RAYNOR MCLAMB RD BUNNLEVEL 28323 T/S: 12/13/2017 09:54 AM SBENNETT -----
B101 01	12/28/17 12/28/17	JH AP	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 003070356 T/S: 12/21/2017 02:15 PM JBROCK ----- T-POLE PASSED -----
B103 01	2/01/18 2/01/18	JH AP	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 003083284 T/S: 01/30/2018 03:29 PM JBROCK -----
P309 01	3/21/18 3/21/18	JH AP	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 003103694 T/S: 03/19/2018 04:14 PM BPETRICH -----
B111 01	3/27/18 3/27/18	JH AP	R*BLDG SLAB INSP/TEMP SVC POLE TIME: 17:00 VRU #: 003106135 T/S: 03/26/2018 10:07 AM BPETRICH -----
R425 01	5/07/18 5/07/18	JH DP	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 003123505 T/S: 05/03/2018 03:30 PM BPETRICH ----- 1)Missing anchor bolts door in garage, back door & front door.2)Nail guard at top plate on water heater wire.3)Nail all holes in structural nail guard over electrical panel in garage.4)Missing hurricane straps on back wall in garage.5)Missing insulation baffles.6)3' head of water on drain line test.7)Seal all holes in air barriers in kitchen & living room.8)Fire caulk wires @ top plate on left wall in living room.9)Nail guards on wires @ top plate on left wall in living room & foyer.Nail guards on wires @ top plate to right of window in right front bedroom.10)Nail & hurricane straps on all 2 & 3 ply trusses per truss documents.11)Fill all holes under tubs.12)100 psi on water line test NO GUAGE.13)Missing smoke dectector in middle bedroom.14)Missing nails in hurricane straps in back left bed closet.15)Need stud under top plate joint in back bed closet.16)Missing bracing on A10,A11,A14 & A15 trusses.17)Nail house wrap per installation instructions. DO NOT SIDE OR INSULATE
R425 02	5/09/18 5/09/18	JH DP	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 003125010 T/S: 05/08/2018 11:16 AM LLUCAS ----- Thank you Lindsey. I did talk with Jimmy regarding insulation baffles and he asked me to call back to the office and ask y'all to put a note on it because he wouldn't remember.

ADDRESS : 955 RAYNOR-MCLAMB RD SUBDIV:
 CONTRACTOR : RED DOOR HOMES OF FAYETTEVILLE PHONE : (910) 672-8900
 OWNER : VLS REAL ESTATE LLC PHONE :
 PARCEL : 12-0556- - -0097- -07-
 APPL NUMBER: 17-50042462 CP NEW RESIDENTIAL (SFD)

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
R425 03	5/11/18 5/11/18	JH DP	ITEMS #1,2,7,9,10 & 17 WERE NOT CORRECTED FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 003126364 T/S: 05/10/2018 01:36 PM BPETRICH ----- ITEMS #10 & 17 NOT CORRECTED
R425 04	5/14/18 5/14/18	JH AP	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 003126794 T/S: 05/11/2018 12:08 PM LLUCAS -----
I129 01	5/17/18 5/17/18	JH CA	R*INSULATION INSPECTION TIME: 17:00 VRU #: 003128071 T/S: 05/15/2018 12:31 PM LLUCAS ----- T/S: 05/16/2018 07:38 AM DJOHNSON ----- CHANGED DATE PER JIMMY HALL PER ALLEN
I129 02	5/18/18 5/18/18	JH DA	R*INSULATION INSPECTION TIME: 17:00 VRU #: 003129202 T/S: 05/17/2018 09:33 AM LLUCAS ----- 1)Need to install door in garage.2)Need to seal around all door frames per code.
I129 03	5/21/18 5/21/18	JH AP	R*INSULATION INSPECTION TIME: 17:00 VRU #: 003129608 T/S: 05/18/2018 11:29 AM LLUCAS -----
H824 01	6/19/18 6/19/18	AC AP	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 003142817 T/S: 06/20/2018 11:53 AM KHINSON ----- T/S: 06/20/2018 11:53 AM KHINSON -----
E209 01	6/22/18 6/22/18	JH DA	R*ELEC TEMP POWER CERT TIME: 17:00 VRU #: 003143328 T/S: 06/21/2018 11:10 AM BPETRICH ----- Electrical incomplete electricians still working.
M305 01	6/22/18 6/22/18	JH AP	R*PLUMB SEWER CONNECTION TIME: 17:00 VRU #: 003143294 T/S: 06/21/2018 11:09 AM BPETRICH -----
P307 01	6/22/18 6/22/18	JH DA	R*PLUMB WATER CONNECTION TIME: 17:00 VRU #: 003143310 T/S: 06/21/2018 11:09 AM BPETRICH ----- LOCK BOX CODE ON PERMIT BOX IS 8900 NOT CONNECTED AT METER
E209 02	6/25/18 6/25/18	DT AP	R*ELEC TEMP POWER CERT TIME: 17:00 VRU #: 003143799 T/S: 06/22/2018 01:21 PM BPETRICH ----- T/S: 06/25/2018 03:23 PM DETAYLOR -----
P307 02	6/25/18 6/25/18	DT AP	R*PLUMB WATER CONNECTION TIME: 17:00 VRU #: 003143807 T/S: 06/22/2018 01:21 PM BPETRICH ----- T/S: 06/25/2018 03:23 PM DETAYLOR -----
R429 01	6/29/18 6/29/18	JH DA	FOUR TRADE FINAL TIME: 17:00 VRU #: 003146040 T/S: 06/28/2018 01:11 PM BPETRICH ----- HOUSE LOCKED
R429 02	7/02/18 7/02/18	JH DA	FOUR TRADE FINAL TIME: 17:00 VRU #: 003146651 T/S: 06/29/2018 02:20 PM BPETRICH ----- LOCK BOX CODE 8900 1)Uncover water cutoff box in pantry & install ring for box 2)AC unit needs to be level & pad needs to sit on grade. 3)Missing handrail for back porch more than 30" at 3'.
R429 03	7/03/18 7-3-18	TI AP JH	FOUR TRADE FINAL TIME: 17:00 VRU #: 003147253 T/S: 07/02/2018 01:32 PM BPETRICH -----

CONTINUED ONTO NEXT PAGE

Lock Box Code 8900