NORTH CAROLINA LICENSING BOARD FOR GENERAL CONTRACTORS

A REQUEST FOR CERTIFIED COPIES OF BUILDING INSPECTION RECORDS

In the Matter of: Carolina Builders	Group of Sanford, LLC
License No.: 78698	Complaint File No.: 19-C-400
	City/County Inspection Department Sheets to be a true and accurate t records for the following address:
This information was requested by Joel Ma Licensing Board for General Contractors. This the	icon, Field Investigator for the North Carolina 2022. X DOWN Signature of Person Completing Form Print Name: Title: Address:
Signed and sworn to before me this day 9 of June, 2022 by Donna Johnson X Dhees M. Jones Notary Public Printed Name of Notary: Theresa M. Jones My Commission Expires:	PLEASE RETURN TO: Scan & Email to: joelmacon@nclbgc.org or US Mail to: Joel Macon, Investigator P.O. Box 413 Carolina Beach, NC 28428

Initial Application Date:_	10	13	17	
----------------------------	----	----	----	--

Application #	17-50042542
	CU#

COUNTY OF HARNETT RESIDENTIAL LAND USE APPLICATION

Central Permitting 108 E. Front Street, Lillington, NC 27546 Phone: (910) 893-7525 ext:2 Fax: (910) 893-2793 www.harnett.org/permits
"A RECORDED SURVEY MAP, RECORDED DEED (OR OFFER TO PURCHASE) & SITE PLAN ARE REQUIRED WHEN SUBMITTING A LAND USE APPLICATION"
LANDOWNER: Rob + Amber TESSIER Mailing Address: 32 Woodhart Circle
City: FURUAY Varing State: NC Zip: 275 86 contact No: 9/9-650-8236 Email: Ttess, er WWS
APPLICANT*: SAMU Mailing Address: Samul. Com
City: State: Zip: Contact No: Email: *Please fill out applicant information if different than landowner
CONTACT NAME APPLYING IN OFFICE: Phone #
PROPERTY LOCATION: Subdivision: Kein Pfeifer State Road # 1412 State Road Name: Christian Light Poad Map Book & Page: 2016 / 388
Parcel: 050633 006 07 PIN: 0033-89-3706-000
Zoning: 2A-30 Flood Zone: X Watershed: GIS Deed Book & Page: 3514 / 189 Power Company':
*New structures with Progress Energy as service provider need to supply premise number
month togress Energy.
PROPOSED USE:
SFD: (Size 6/ x 47) # Bedrooms: 4 # Baths: 3 Basement(w/wo bath): 0 Garage: 3 Deck: Crawl Space: Slab:
Mod: (Sizex) # Bedrooms # Baths Basement (w/wo bath) Garage: Site Built Deck: On Frame Off Frame (Is the second floor finished? () yes () no Any other site built additions? () yes () no
Manufactured Home:SWDWTW (Sizex) # Bedrooms: Garage:(site built?) Deck:(site built?)
□ Duplex: (Sizex) No. Buildings: No. Bedrooms Per Unit:
□ Home Occupation: # Rooms: Use: Hours of Operation: #Employees:
Addition/Accessory/Other: (Sizex) Use: Closets in addition? () yes () no
Water Supply: X County Existing Well New Well (# of dwellings using well) *Must have operable water before final
Sewage Supply: X New Septic Tank (Complete Checklist) Existing Septic Tank (Complete Checklist) County Sewer
Does owner of this tract of land, own land that contains a manufactured home within five hundred feet (500') of tract listed above? () yes (X) no
Does the property contain any easements whether underground or overhead () yes (X) no
Structures (existing or proposed): Single family dwellings: Manufactured Homes: Other (specify):
Required Residential Property Line Setbacks: Comments:
Required Residential Property Line Setbacks: Comments:
Rear 2S 95'
Closest Side 10 33'
Sidestreet/corner tot 20 /\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
Nearest Building 10 N A

on same lot

SPECIFIC DIRECTIONS TO THE PROPERTY FROM LILLINGTON:
401 N. towards FURNAY
LEFT ON Christian Light Rd
Stay ON Christian Light past Kipling Roap
Lot is on left between Jessie Lee LANG AND HArdee Rd.
Existing home @ 5237 Christian Light is the last house
prior to the lot.
If permits are granted I agree to conform to all ordinances and laws of the State of North Carolina regulating such work and the specifications of plans submitted
I hereby state that foregoing statements are accurate and correct to the best of my knowledge. Permit subject to revocation if false information is provided.
Robert TESSIE 10/10/12
Signature of Owner or Owner's Agent Date

^{***}It is the owner/applicants responsibility to provide the county with any applicable information about the subject property, including but not limited to: boundary information, house location, underground or overhead easements, etc. The county or its employees are not responsible for any incorrect or missing information that is contained within these applications.***


^{**}This application expires 6 months from the initial date if permits have not been issued**


NAM	E:	Tessi	W				AP	PPLICATION #:_17-50042542
			This application to be fil	led o	ut when a	pplying for	r a se	eptic system inspection.*
<u>C</u>	ount	y Health De	partment Application	n fo	r Impro	vement I	Perm	nit and/or Authorization to Construct
IF TH	E INFO	ORMATION IN	THIS APPLICATION IS FA	LSIF	TED, CHAI	NGED, OR T	THES	SITE IS ALTERED, THEN THE IMPROVEMENT
depend	ding up	on documentati	on submitted. (Complete site	plan	= 60 month	is: Complete	ne per	ermit is valid for either 60 months or without expiration
,	91	0-893-7525 c	ption 1	1		,	CO	= without expiration # 10/13 024366
√ E	nviro	nmental Hea	alth New Septic Syster	nCo	de 800			
•	All	property in	ons must be made vis	ible	. Place "	pink prope	erty fl	lags" on each corner iron of lot. All property
			early flagged approxima					
•	OU	t buildings, sy	vimming pools etc. Pla	ce fl	ans per s	ne propos ite plan de	ed St	tructure. Also flag driveways, garages, decks ped at/for Central Permitting.
								ewed from road to assist in locating property.
	If p	property is thi	ckly wooded, Environm	enta	Health re	equires tha	at you	ou clean out the undergrowth to allow the soil
	eva	aluation to be	performed. Inspectors	sho	uld be abl	e to walk f	reely	y around site. Do not grade property.
•	All	tots to be a	ddressed within 10 bu	sine	ss days	after conf	<u>irma</u>	ation. \$25.00 return trip fee may be incurred
	Aft	er preparing	proposed site call the vi	nou	nermitting	svetem a	1 910	rty lines, etc. once lot confirmed ready. 0-893-7525 option 1 to schedule and use code
	80	0 (after selec	ting notification permit i	f mu	Itiple peri	mits exist)	for E	Environmental Health inspection. Please note
	COL	nfirmation nu	mber given at end of red	ordi	ng for pro	of of reque	est.	
•							d to (Central Permitting for permits.
			alth Existing Tank Insp					
•	Pro	now above in	structions for placing fla	gs a	na cara o	n property	nk a	us diagram indicates, and lift lid straight up (ii
	po.	ssible) and th	en put lid back in plac	e. (L	Inless ins	pection is	for a	is englam moleates, and in its straight up (in septic tank in a mobile home park)
•			LIDS OFF OF SEPTIC TA			F		topio tam ma modilo nomo pam,
•	if r	nultiple perm	nits, then use code 800	for	Environn	system at nental Hea	910- alth i	 -893-7525 option 1 & select notification permit inspection. Please note confirmation number
			recording for proof of recording for type to be a recording for proof of recording for the condition of the			d procood	10.0	Central Permitting for remaining permits.
SEPT		e Click2Guv	of IVA to fleat results. C	nce	approved	ı, proceed	10 0	entral Permitting for remaining permits.
If app	lying !							ranked in order of preference, must choose one.
			() Innovative					_) Any
{_}}	Alter	native	{}} Other				_	
			the local health departmen "yes", applicant MUST A					tion if any of the following apply to the property in CUMENTATION:
{_}}	'ES	K) NO	Does the site contain any	Juris	dictional V	Wetlands?		
{}}		(X) NO	Do you plan to have an in	igati	on system	now or in t	he fu	iture?
{}}	YES	X) NO	Does or will the building	conta	ain any <u>dra</u>	ins? Please	expla	ain
1_1	YES	X) NO	Are there any existing we	11s, s	prings, wa	terlines or \	Waste	ewater Systems on this property?
{}}	YES	X) NO	Is any wastewater going t	o be	generated	on the site of	other	than domestic sewage?
{}}	'ES	{ ∠ } NO	Is the site subject to appro	val t	y any othe	er Public A	gency	y?
(_)	ES	(X) NO	Are there any Easements	or Ri	ght of Wa	ys on this p	roper	rty?
{_}}	YES	(≯) №	Does the site contain any	exist	ing water,	cable, phor	ne or	underground electric lines?
			If yes please call No Cut	at 8	00-632-49	49 to locate	the I	lines. This is a free service.
I Have	Read	This Applicati	on And Certify That The In	form	ation Prov	ided Herein	Is Tr	rue, Complete And Correct. Authorized County And
State (Officia	s Are Cranted	Right Of Entry To Conduc	t Nec	essary Inci	nections To	Deter	rmine Compliance With Applicable Laws And Rules

I Have Read This Application And Certify That The Information Provided Herein Is True, Complete And Correct. Authorized County And State Officials Are Granted Right Of Entry To Conduct Necessary Inspections To Determine Compliance With Applicable Laws And Rules. I Understand That I Am Solely Responsible For The Proper Identification And Labeling Of All Property Lines And Corners And Making The Site Accessible So That A Complete Site Evaluation Can Be Performed.

The Site Accessible So That A Complete Site Evaluation Can Be Performed,

| Lo-C | Tess | Ferror |
| PROPERTY OWNERS OR OWNERS LEGAL REPRESENTATIVE SIGNATURE (REQUIRED)





Adams Soil Consulting 1676 Mitchell Road Angier, NC 27501 919-414-6761

November 22, 2016 Project # 437

Mauldin-Watkins Surveying, P.A. P.O. Box 444 1301 W. Broad Street Fuquay-Varina NC 27526

RE: Preliminary soil/site evaluation for Lot 1 of the minor subdivision for Kevin and Christine Pheifer located adjacent to Christian Light Road in Harnett County.

Mr. Mauldin,

Ĺ

Adams Soil Consulting (ASC) conducted a preliminary soil evaluation on the above referenced parcel to determine the areas of soils which are suitable for subsurface wastewater disposal systems (conventional & LPP). The soil/site evaluation was performed using hand auger borings during moist soil conditions and sketched onto a preliminary plat supplied by Mauldin - Watkins, P. A. Surveying.

The suitable soils shown on the accompanying soil map are suitable for a conventional type initial and repair area for at least one 4-bedroom home. The lot contains greater than 12,000 ft² of suitable soils that consist of clay subsoil that can support a daily loading rate of 0.25-0.35 gallons/day/ft². The specific septic system and loading rates for this lot will be permitted by the Harnett County Health Department. The areas for the proposed septic fields shall not be impacted by home sites, pools, garages and shall not be mechanically altered from the natural lay of the land. A lot should accommodate a house foot print of at least 60' x 60'. Due to the limited amount of potentially suitable soil found on the lot a preliminary septic system design was completed and is show on the accompanying soil map. The design is only a concept; the actual septic system will need to be planned with the final house location and site plan.

The lot will require a detailed soils evaluation by the Harnett County Health Department prior to issuance of any permits for a septic system. A septic system layout may be required before a permit can be issued on the above referenced lot demonstrating available space for the primary and repair septic areas. Due to the subjective nature of the permitting process and the variability of naturally occurring soils, Adams Soil Consulting cannot guarantee that areas delineated as suitable for on-site wastewater disposal systems will be permitted by the governing agency. The lot may require a septic system utilizing pumps, shallow or ultra-shallow conventional trench placement, low pressure pipe system, and/or reductions system for final approval. The accompanying soil map is preliminary in nature, no further assumptions or subdivision should be made without a more detailed evaluation.

If you have any questions regarding the findings on the attached map or in this report, please feel free to contact me anytime. Thank you allowing me to perform this site evaluation for you.

Sincerely,

Alex Adams

NC Licensed Soil Scientist #1247

Encl: Soil Map



HARNETT COUNTY CASH RECEIPTS
CUSTOMER RECEIPT

Oper: BPETRICH Type: CP Drawer: 1
Date: 18/13/17 51 Receipt no: 116867

Year Number 2017 50042542 92941 TECH 4 LILLINGTON, NC 27546 B4 BP - ENV HEALTH FEES

Amount

NEW TANK

\$750.00

ROBERT & AMBER TESSIER

Tender detail CK CHECK PAYMEN Total tendered Total payment 27756 \$758.88 \$758.88 \$758.88

Trans date: 18/13/17 Time: 9:21:49

** THANK YOU FOR YOUR PAYMENT **


нте#_17-5-43543

Harnett County Department of Public Health

Improvement Permit

A build	ling permit cannot be issued with on	ly an Improvement	Permit	(sa (412)
ISSUED TO: Robd Ambes Tessier	PROPERTY LOCATION	: Christi	on light nd	(3/1/4/2)
NEW □ REPAIR □ EXPANSION □		a Improvements re	mired miles to Construction Audi	LOI #
Type of Structure: 437 GIX44'5	١١١١ ـــ	e improvements re-	quired prior to Construction Aut	norization issuance:
Proposed Wastewater System Type: 25% N. 5				
Projected Daily Flow: 480 GPD				
Number of bedrooms: 4 Number of Occupants:	8			
Basement Yes No	max			
\$2.000,000,000 degree degree degree degree de la constant de la co		/ / · · r ·		
Pump Required: Yes No May be required I				
Type of Water Supply: Community Public Permit conditions:	well Distance from well		Permit valid for:	☐ Five years☐ No expiration
Authorized State Agent::	For Nat Date:	101251	2017 (ATTACHED SITE SKETCH
The issuance of this permit by the Health Department in no way guarantees to site is subject to revocation if the site plan, plat, or the intended use changes the Laws and Rules for Sewage Treatment and Disposal and to conditions of the	he issuance of other permits. The permit holds . The Improvement Permit shall not be affecte	er is responsible for che	cking with appropriate governing bodies	in meeting their requirements. This
	Construction Author	orization		
	(Required for Building I			
The construction and installation requirements of Rules .1950, .1952, .1954, .1			into this narmit and shall be mot Susti	ome shall ha installed in assessment
with the attached system layout.				
ISSUED TO: Robd Amber Tessiec	PROPERTY LOC	CATION: Chr.	stim Light Rd.	(SR 1412)
Facility Type: 432 GI'X 44' SITS	JUDUINISIUM _			LUI # _/
		☐ Repair		
Basement? Yes No Basement Fixtures	The second secon			
Type of Wastewater System** 25% Ne	dichech Syste	M	(Initial) Wastewater Flow	r: 480 GPD
(See note below, if applicable)				
- 25% red	Ction System (Re	epair)		
Installation Requirements/Conditions Nu	mber of trenches 3	1 /		
3	act length of each trench 16		Trench Spacing: 9	Cont on Contar
	nches shall be installed on contou		Soil Cover: 13	24 E300000
	ximum Trench Depth of: 24		(Maximum soil cover shal	
(Tr	ench bottoms shall be level to +	/-1/4"	36" above the trench be	ottom)
in	all directions)			
Pump Requirements:ft. TDH vs GF	M			inches below pipe
			Aggregate Depth:	inches above pipe
Conditions:			Aggregate Deptil.	
			_	inches total
WATER LINES (INCLUDING IRRIGATION) WAS READ				
WATER LINES (INCLUDING IRRIGATION) MUST BE 10	FT. FROM ANY PART OF SEPTI	C SYSTEM OR F	EPAIR AREA.	
NO UTILITIES ALLOWED IN INITIAL OR REPAIR DRAIN	I FIELD AREA.			
**If applicables I understand the system two area (C.I.)	······································	.,	, , , , , ,	
**If applicable: I understand the system type specified is d	merent from the type specified of	n the application.	I accept the specifications of	f this permit.
Owner/Legal Representative Signature:			Date:	
This Construction Authorization is subject to revocation if the site plan, plat, or	the intended use changes. The Construction 2	Authorization shall not b	e transferred when there is a change in	nownership of the site. This
Construction Authorization is subject to compliance with the provisions of the Li				E ATTACHED SITE SKETCH
	0			menes site shereil
Authorized State Agent:		, n.	1211	
	THET NEIT	Date:	10/05/20	014
ANDREW CURRIN	Construction Authorization	on Expiration D	ate: 10/25/20	233

Harnett County Department of Public Health Site Sketch



Code: Elle #: On-Site Wastewater Section :# 107 Property ID: Division of Environmental Health Sheet: Department of Environment, Health and Natural Resources

OTHER SOIL MORPHOLOGY Ł 0 В ☐ Pit ☐ Recess ☐ Industrial Process Sewage DəxiM 🗌 Type of Wastewater: Evaluation Method: Auger Boring Ju 🗌 Owner: Applicant: Appl gning2 Other Property Size: 3, 34 At SES TISE HE CUS 7358 81 for ON-SITE WASTEWATER SYSTEM SOIL/SITE EVALUATION

5	Agu la	7:05 6	more som	Q: Classification (.1948); Evaluated By: Others Present:	اله المداط م. ع	इ.ठ ६५०३	62		əldaliavA ÇT mətayê AATA əriê
				Other Factors (.1946):	pair System	ial Rep	inf sv2	иој	Descripti
									1
									-
					150 5 51 05				
				20	Husna	1100	mos	4	
			+ (व मालेश ड	1,00 201	wart, w	151100		-
				()	(+ > -) - / -	Lost	3000	21:00	*
							1		
				1	h				
28.0			en	754081640"	1360513	7 716	18h-00		
Sd									-
70					19 24 m	57 10	JE-0		8,
50			38	98: 7110115.1	001111	~	- 5 10		
2 >			20	1.54 ATT 36"	109.4	7 7168	8E-61		
9					Sty HIS WA	57 707	61.0		8
							C, .		
SE.0			38		333511	> 7181	SE-he		
58					3-1545 DA	57 20	he-0	7	12/1
& LTAR	sinoH	Class	Depth (IN.)	Color	Mineralogy	Texture			
Profile	1944 1944	olde2	E491. Tio2	Soil	.1941 Consistence	1491, Sintourit	Depth (In.)	Position/ % oqol2	# E
20180 010			OFILE FACTORS	1945			noziroH	Landscape	7
1		2	OEII E EVCLUB	ad	1941	NIN THOS		0461	1

Site LTAR

HTE# 17-5-42542

Harnett County Department of Public Health

25695

PERMIT # 29246

Operation Permit

Mew Installation 🖾 Septic Tank 🖾 Nitrification Line 🗆 Repair 🗀 Expansion	1
PROPERTY LOCATION: 5311 Christian Light Rd. (Sr. 1416	3)
Name: (owner) (Lob & Anker Tessier SUBDIVISION LOT # 1	
System Installer: Five County well & Septic Registration #	
Basement with plumbing: Garage Rumber of Bedrooms	
Type of Water Supply: Community Public Well Distance from well feet System Type: Types V and VI Systems expire in 5 years	
System Type: 25% and VI Systems expire in 5 years. (In accordance with Table V a) Owner must contact Health Department 6 months prior to expiration for permit renewal.	
owner-was contact nearth bepartment o months prior to expiration for permit renewal.	
This system has been installed in compliance with applicable North Carolina General Statutes, Rules for Sawage Treatment and Disposal, and all conditions of the Improvement Permit and Construction Authorization.	
/ .2	
23 - Jan - 23'-	
No N	
1 2 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
200 200 / 200 200 SSI	
1 3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
HOL SED	
PORCH TO CHRISTIAN LIC	11
2 RD (SZIMIZ)	1
YAW 31	1
	+
PERMIT CONDITIONS:	_
I. A Berformance: System shall perform in accordance with Rule .1961.	_
II. Monitoring: As required by Rule .1961.	
III. Maintenance: As required by Rule .1961. Other:	
Vihiturace system operator required? Yes No.	
Subsurface system operator required? Yes No W	
If yes, see attached sheet for additional operation conditions, maintenance and reporting.	
If yes, see attached sheet for additional operation conditions, maintenance and reporting. IV. Operation:	
If yes, see attached sheet for additional operation conditions, maintenance and reporting.	
If yes, see attached sheet for additional operation conditions, maintenance and reporting. V. Other:	,
If yes, see attached sheet for additional operation conditions, maintenance and reporting. V. Other: D-Box D-Box Pump D-Alorm D-Box PWR Lin	ì
If yes, see attached sheet for additional operation conditions, maintenance and reporting. V. Other: D-Box	a)
If yes, see attached sheet for additional operation conditions, maintenance and reporting. V. Other: D-Box Pump Alorm H20Line PWR Lin Following are the specifications for the sewage disposal system on the above captioned property. Type of system: Conventional Other FZ FLOW HS Septic Tank: gallons Pump Tank: gallons Subsurface No. of exact length width of depth of	a)
If yes, see attached sheet for additional operation conditions, maintenance and reporting. V. Other:	3
If yes, see attached sheet for additional operation conditions, maintenance and reporting. V. Other: D-Box	ð
If yes, see attached sheet for additional operation conditions, maintenance and reporting. V. Other:	D. Communication of the Commun

Harnett County Central Permitting
PO Box 65 Lillington NC 27546
910 893 7525 Fax 910 893 2793 www.harnett.org/permits

Application # 42542

Each section below to be filled out by whomever performing work Must be owner or licensed contractor Address company name & phone must match

Application for Residential Building and Trades Permit

Owner's Name ROBERT + AMBER TESSIER	Date 7-17-18
Site Address 5311 CHRISTIAN LIGHT PD. FUQUAY VAR	NA, NC Phone 910-973-8355
Directions to job site from Lillington Go 45 401 NaCTH Go AF	plox. 3 miles + Tuen left onto
CHRISTIAN LIGHT RD5311 CHRISTIAN LIGHT RD.	will be on the left
Subdivision W/A	Lot
Description of Proposed Work NEW SINGLE FAMILY	# of Bedrooms 4
Heated SF 2, 424 Unheated SF Finished Bonus Room? _/ General Contractor Information	
Gitto Enterprises	919.809 2860
Building Contractor's Company Name	Telephone
7320 Bassett Hall Court Raleigh NC	Gittopm @Gmail, cor
Address 27616	Email Address
81942 License #	
Electrical Contractor Information	on .
Description of Work NEW SINGLE FAMILY Service Size	200 Amps T-Pole Yes No
ARGUIJO ELECTRIC	919-264-8287
Electrical Contractor's Company Name	Telephone
4424 RIVER ENGE DR. RAPRIGH, NC 27404	arguiso, ELECTRIC Panail Con Email Address
29138 · 4	Email Address
License #	
Mechanical/HVAC Contractor Inform	nation
Description of Work NEW SINGLE FAMILY	
CAROLINA AIR HEATING + COOLING	910-947-7707
Mechanical Contractor's Company Name	Telephone
3700 US HWY 15-501 CARTHAGE, NC 28327	Kelly & CardinaAir. Com
Address 235 49	Email Address
License #	
Plumbing Contractor Information	<u>on</u>
Description of Work NEW SINGLE FAMILY	# Baths 2 3/4
RICHARD DONALD WHITE	919-497-6869
Plumbing Contractor's Company Name	Telephone
1020 BAPTIST CHURCH RD. BUNN, NC	Telephone Cinthya.ugarte Qicland, Can Email Address
Address	Email Address
16941 License #	
Insulation Contractor Information	
PRIME ENERGY GROUP 2300 WESTINGHOUSE RULL. Insulation Contractor's Company Name & Address PALECH, NC.	919-882-1324
	Telephone
27604	

I hereby certify that I have the authority to make necessary application that the application is correct and that-the construction will conform to the regulations in the Building Electrical Plumbing and Mechanical codes and the Harnett County Zoning Ordinance. I state the information on the above contractors is correct as known to me and that by signing below I have obtained all subcontractors permission to obtain these permits and if any changes occur including listed contractors site plan number of bedrooms building and trade plans. Environmental Health permit changes or proposed use changes. I certify it is my responsibility to notify the Harnett County Central Permitting Department of any and all changes.

EXPIRED PERMIT FEES - 6 Months to 2 years permit re-issive fee is \$150.00. After 2 years re-issue fee.

is as per current fee schedule Signature of Owner/Contractor/Officer(s) of Corporation Affidavit for Worker's Compensation N C G S 87-14 The undersigned applicant being the General Contractor _____ Owner _____ Officer/Agent of the Contractor or Owner Do hereby confirm under penalties of perjury that the person(s) firm(s) or corporation(s) performing the work set forth in the permit Has three (3) or more employees and has obtained workers compensation insurance to cover them Has one (1) or more subcontractors(s) and has obtained workers compensation insurance to cover them Has one (1) or more subcontractors(s) who has their own policy of workers compensation insurance covering themselves Has no more than two (2) employees and no subcontractors While working on the project for which this permit is sought it is understood that the Central Permitting Department issuing the permit may require certificates of coverage of worker's compensation insurance prior to issuance of the permit and at any time during the permitted work from any person firm or corporation carrying out the work Company or Name CAROLINA BUILDERS GROUP of SAFERY, UC CHRIS LAYTOR MEMBER MGR. Date 7-17-18 Sign w/Title

July 17, 2019

Harnett County Central Permitting 108 E. Front Street Lillington, NC 27546

SUBJECT:

5311 Christian Light Road

Fuquay Varina, NC 27526

To Whom It May Concern:

Effective immediately, Gitto Enterprises, License # 81942, will be taking over the construction of the house located at 5311 Christian Light Road.

Please call with any questions.

Respectfully,

Rob Tessier 919-650-8236

rtessierwws@gmail.com

NC Registered Engineering Firm # F-1078



ECS Southeast, LLP 6151 Raeford Road Suite A

Fayetteville, NC 28304 (910) 401-3288 [Phone] (910) 323-0539 [Fax]

LETTER OF TRANSMITTAL

September 11, 2018

Carolina Builders Group 4699 Hwy 87 S Sanford, NC 27332

ATTN: Accounts Payable

RE: 5311 Christian Light Road Foudation

ECS Job # 33:4552

Permits:

Location: 5311 Christian Light Road

Fuquay- Varina, NC

We are enclosing:

X Field Reports

X For your use

X As requested

ENCL:

Field Report # 1

Project Engineer


09/10/2018

A DOWN

Mengo Crawleg

Field Services Manager

Uhristian Light Rd. Work: 47096 Project: 4552 Eric M. Barber Jr. 09-10-18



Legend (NTS) (CRAWLSPACE FOUNDATION PLAN

- Foundation evaluation (H): DLP LOCATION

Wis set statemen.	R RESUMENCE	TESSIER RESULENCE	100	MR PLINA BL (LINES) MR 1 - March 1997 MR 2 - Marc
R RESIDENCE	TESSIER RESULENCE	CRAWLSPACE FOUNDATION PLAN 06/13/2018 18"=1-0" U.M.O.		the to prompte
TERSIER RESIDENCE		CRAWL SPACE FOLINDATION PLAN 06/13/2018 1/8"=1"-0" U.N.O.	\$ AAA	
	CRAWLSPACE FOUNDATION PLAN	06/13/2018 1/8"=1"-0" U.N.O.	and decreasing the	TE SSIER PESSIA NOS



Project: 5311 Christian Light Road Foudation	Project No.	4552
Location: 5311 Christian Light Road	Day/Date:	09/10/18
Fuguay- Varina - Harnett County - NC - 27526		

Contractor: None Listed

		Size (V	V x H x L)	Footing Bott	om Elevation		Required Blow Counts	
Footing Number	Location	Design	Actual	Design	Depth of Undercut (in)	Description of Subgrade Material	# of Blows / increment	Design Bearing Pressure
3	3	хх	хх	3000	0 .	Red / orange	6	
						sand	4.9,12	
2	3	хх	хх	3000	-1 .	Red / orange	6	
3						clay	8,12,12	
3	3	хх	x x	2000	-2 .	Red / orange	6	
3							10,25+,25+	
3	3	x x	x x	3000	-3 .	Red / orange	6	
3							11,25+,25+	
	4	x x	x x	3000	0 .	Red / orange	6	
4							3,4,7	1
	4	хх	x x	3000	-1 .	Red / orange	6	
4							7,12,17	1
	4	x x	x x	3000	-2 .	Red / orange	6	
4		100					HAR	1
-	5	x x	хх	3000	0 .	Red / orange	6	
5							6,7,11	1

Eric Michael Barber, Jr.
ECS Southeast, LLP



ECS Southeast, LLP 6151 Raeford Road Suite A Fayetteville, NC 28304 (910) 401-3288 [Phone] (910) 323-0539 [Fax]

LETTER OF TRANSMITTAL

September 13, 2018

Carolina Builders Group 4699 Hwy 87 S Sanford, NC 27332

ATTN: Accounts Payable

RE: 5311 Christian Light Road Foudation

ECS Job # 33:4552

Permits:

Location: 5311 Christian Light Road

Fuquay- Varina, NC

Dennis D Lowery, P.E.

Project Engineer

We are enclosing:

Field Reports

For your use

As requested X

ENCL:

Field Report #2

09/12/2018

Dennis D Ldwer

Project Engineer

NIS D. LON WIND D. LOWIN



ECS Southeast, LLP

6151 Raeford Road Suite A Fayetteville, NC 28304 (910) 401-3288 [Phone] (910) 323-0539 [Fax]

Project

5311 Christian Light Road Foudation

Location

Fuquay- Varina, NC

Client

Carolina Builders Group - Accounts Payable

FIELD REPORT

Project No.

33:4552

Report No.

2

Day & Date

Wednesday 09/12/2018

Weather

75°/ Cloudy

On-Site Time

0.50

Lab Time

Travel Time*

0.00 0.00

Total

0.50

Re Obs. Time

0.00

Remarks

Trip Charges*

Tolls/Parking*

Mileage*

Time of

Departure Arrival

08:45A

09:15A

Chargeable Items

Summary of Services Performed (field test data, locations, elevations & depths are estimates) & Individuals Contacted.

ECS Project Engineer arrived on site as requested to observe the widths and depths of the perimeter continious footings and interior peir footings, prior to the placement of concrete.

The continious footing and pier footings were excavated and met the depths and witdths that were specified in the plans that were provided by the contractor.

The recommendations that were made by ECS on the report 1, have been perfored by the contractor.

Its in the opinion of ECS that the dimensions for the minimum widths and depths of the excavated footings for the residential foundation meet the required plans and specifications prior to the placement of concrete.

^{*} Travel time and mileage will be billed in accordance with the contract.



Project: 5311 Christian Light Road Foudation	Project No.	4552
Location: 5311 Christian Light Road	Day/Date:	09/10/18
Fuquay- Varina - Harnett County - NC - 27526		

Contractor: None Listed

		Size (W x H x L)		Footing Bottom Elevation				Required Blow Counts	
Footing Number	Location	Design	Actual	Design	Depth of Undercut (in)		Description of Subgrade Material	# of Blows / increment	Design Bearing Pressure
5	5	5 x x x x 3	3000	-1 .		Red / orange	6		
								8,16,22	
5	5	хх	хх	3000	-2 .		Red / orange	6	
								25+,25+,25+	
5	5	хх	хх	3000	-3 .		Red / orange	6	
								HAR	

Ву:	Eric Michael Barber, Jr.						
	ECS Southeast, LLP	_					



Project: 5311 Christian Light Road Foudation	Project No.	4552
Location: 5311 Christian Light Road	Day/Date:	09/10/18
Fuquay- Varina - Harnett County - NC - 27526		

Contractor: None Listed

		Size (W x H x L)		Footing Bott	Footing Bottom Elevation			Required Blow Counts	
Footing Number	Location	Design	Actual	Design	Depth of Undercut (in)		Description of Subgrade Material	# of Blows / increment	Design Bearing Pressure
1	1	x x	хх	3000	0 .		Red / clay	6	
'								26,15,16	<u> </u>
1	1	x x	x x	3000	-1 .		Red / orange	6	
							clay	16,25+,25+	
- 1	1	хх	хх	3000	-2 .		Red / orange	6	
'							clay	25+,25+,25+	
1	1	хх	x x	3000	-3 .		Red / orange		
'							clay	25+,25+,25+	1
2	2	x x	хх	3000	0 .		Red / orange	6	
2							clay	9,8,9	
2	2	x x	x x	3000	-1 .		Red / orange]
2							clay	25+,25+,25+	
2	2	x x	x x	3000	-2 .		Red / orange	6	
2							clay	11,14,25+	
2	2	x x	x x	3000	-3 .		Red / orange	- 6	
2							clay	15,18,19	

Ву:	Eric Michael Barber, Jr.						
	ECS Southeast, LLP						



ECS Southeast, LLP 6151 Raeford Road Suite A Fayetteville, NC 28304 (910) 401-3288 [Phone] (910) 323-0539 [Fax]

Project

5311 Christian Light Road Foudation

Location

Fuquay- Varina, NC

Client

Carolina Builders Group - Accounts Payable

Remarks

Trip Charges* Chargeable Items

Tolls/Parking*

Mileage*

Time of

Total

Project No.

Report No.

Day & Date

On-Site Time

Travel Time*

Re Obs.Time

Weather

Lab Time

Arrival

FIELD REPORT

33:4552

91º/ Cloudy

2.75

0.00

0.00

2.75

0.00

Departure

Monday 09/10/2018

08:45A 11:30A

* Travel time and mileage will be billed in accordance with the contract.

Summary of Services Performed (field test data, locations, elevations & depths are estimates) & Individuals Contacted.

An ECS representative arrived on site, as requested, to check the bearing capacity of soils via hand auger/dcp method for Christian Light Road Foundation. Please see the attached sketch.

A hand auger was used to advance the boreholes to different depths noted on the boring logs. Dynamic Cone Penetrometer (DCP) test were performed in the hand auger boreholes by a 1.5 inch diameter cone driven into the soil by a 15 pound ring weight with a free fall of 20 inches. The number of blows required to drive the cone into the soil a distance of 1.75 inches is termed the DCP Value and is indicated for each test on the hand auger.

A total of 5 hand auger/DCP evaluations were performed and did appear to be suitable to support the design bearing capacity of 3,000 psf.

The soil in place is suitable to support the structural, however some water was encountered therefore ECS recommends to remove 12 inches of the existing soil in the areas that are highlighted on the sketch. When the soil is removed ECS recommends to replace the soil with 57 stone or a similar wash stone back to the proposed grade, and to install a French drain at the rear side of the property to allow the water to drain away from the structure.

ECS will return, as requested, to perform additional services.

NC Registered Engineering Firm # F-1078



ECS Southeast, LLP 6151 Raeford Road Suite A Fayetteville, NC 28304 (910) 401-3288 [Phone] (910) 323-0539 [Fax]

LETTER OF TRANSMITTAL

September 11, 2018

Carolina Builders Group 4699 Hwy 87 S Sanford, NC 27332

ATTN: Accounts Payable

RE: 5311 Christian Light Road Foudation

ECS Job # 33:4552

Permits:

Location: 5311 Christian Light Road

Fuquay- Varina, NC

We are enclosing:

X Field Reports

For your use

As requested

ENCL:

Field Report # 1

09/10/2018

A A A A


Dennis D Eowa.
Project Engineer.
Project Enginee

Mingo Cowley Donny Johnson

Field Services Manager

Christian Light Rd. Work: 47096 Project: 4552

Eric M. Barber Jr. 09-10-18



Legend (NTS) (CRAWLSPACE FOUNDATION PLAN

Foundation evaluation

(H) = DCP Location

	ARCHINA BE (LD) AND MANAGEMENT OF THE STREET
The second secon	remarker trade deads. They have been
The second color of the second	
-	eritine de principal
-	
1	zu Jant Intgolehnow
4 4	
doi integrand-sor	EBBIER RESIDENCE
į	<u> </u>
CF	PRAWLSPACE OF INDIATION PLAN
2	06/13/2019
-	1/8"=1"-0" U.N.O.
Ē	TE
-	TE181001



Project: 5311 Christian Light Road Foudation	Project No.	4552
Location: 5311 Christian Light Road	Day/Date:	09/10/18
Fuguay- Varina - Harnett County - NC - 27526		

Contractor:	None Listed	

		Size (V	V x H x L)	Footing Bott	om Elevation			Required Blow Counts		
Footing Number	Location	Design	Actual	Design	Depth of Undercut (in)		Description of Subgrade Material	# of Blows / increment	Design Bearing Pressure	
3	3	хх	хх	3000	0 .		Red / orange			
							sand	4.9,12		
3	3	хх	хх	3000	-1 .	Red / orange	6			
J							clay	8,12,12		
3	3	хх	хх	2000	-2 .		Red / orange	6		
٦								10,25+,25+		
3	3	хх	x x	3000	-3 .		Red / orange	6		
3								11,25+,25+	1	
4	4	хх	x x	3000	0 .	. Red / orang	Red / d	Red / orange	6	
4								3,4,7	1	
4	4	хх	x x	3000	-1 .		Red / orange	6		
4								7,12,17	1	
4	4	хх	хх	3000	-2 .	Red / orange	6			
4								HAR	1	
-	5	x x	хх	3000	0.	0 . Red / orange	Red / orange	6		
5		10000						6,7,11	1	

Ву:	Eric Michael Barber, Jr.							
	ECS Southeast, LLP							



ECS Southeast, LLP

6151 Raeford Road Suite A Fayetteville, NC 28304 (910) 401-3288 [Phone] (910) 323-0539 [Fax]

LETTER OF TRANSMITTAL

September 13, 2018

Carolina Builders Group 4699 Hwy 87 S Sanford, NC 27332

ATTN: Accounts Payable

RE: 5311 Christian Light Road Foudation

ECS Job # 33:4552

Permits:

Location: 5311 Christian Light Road

Fuquay- Varina, NC

We are enclosing:

X Field Reports

For your use

As requested X

ENCL:

Field Report # 2

09/12/2018

NIS D. LOY

Project Eng

Dennis D Lowery, P.E. Project Engineer



ECS Southeast, LLP

6151 Raeford Road Suite A Fayetteville, NC 28304 (910) 401-3288 [Phone] (910) 323-0539 [Fax]

Project

5311 Christian Light Road Foudation

Location

Fuquay- Varina, NC

Client

Carolina Builders Group - Accounts Payable

FIELD REPORT

Project No.

33:4552

Report No.

Day & Date

Wednesday 09/12/2018

Weather

75°/ Cloudy

On-Site Time

Lab Time

0.50 0.00

Travel Time*

0.00

Total

0.50

Re Obs.Time

0.00

Remarks

Trip Charges*

Tolls/Parking*

Mileage*

Time of

Departure Arrival

08:45A

09:15A

Chargeable Items

Summary of Services Performed (field test data, locations, elevations & depths are estimates) & Individuals Contacted.

ECS Project Engineer arrived on site as requested to observe the widths and depths of the perimeter continious footings and interior peir footings, prior to the placement of concrete.

The continious footing and pier footings were excavated and met the depths and witdths that were specified in the plans that were provided by the contractor.

The recommendations that were made by ECS on the report 1, have been perfored by the contractor.

Its in the opinion of ECS that the dimensions for the minimum widths and depths of the excavated footings for the residential foundation meet the required plans and specifications prior to the placement of concrete.

^{*} Travel time and mileage will be billed in accordance with the contract.



Project: 5311 Christian Light Road Foudation	Project No.	4552
Location: 5311 Christian Light Road Fuquay- Varina - Harnett County - NC - 27526	Day/Date:	09/10/18
Contractor: None Listed		

		Size (V	V x H x L)	Footing Bott	om Elevation		Required Blow Counts	
Footing Number	Location	Design	Actual	Design	Depth of Undercut (in)	Description of Subgrade Material	# of Blows / increment	Design Bearing Pressure
5	5	x x	хх	3000	-1 .	Red / orange	6	
							8,16,22	1
5	5	хх	x x	3000	-2 .	Red / orange	6	
J							25+,25+,25+	1
5	5	хх	хх	3000	-3 .	Red / orange	6	
3							HAR	1

Eric Michael Barber, Jr.								
	ECS Southeast, LLP							

Contractor: None Listed



Report of Spread Footing - Foundation Observations

Project: 5311 Christian Light Road Foudation	Project No. 4552	
Location: 5311 Christian Light Road	Day/Date: 09/10/18	
Fuguay- Varina - Harnett County - NC - 27526		

		Size (V	V x H x L)	Footing Bott	om Elevation		Required Blow Counts	
Footing Number	Location	Design	Actual	Design	Depth of Undercut (in)	Description of Subgrade Material	# of Blows / increment	Design Bearing Pressure
1	1	x x	хх	3000	0 .	Red / clay		1
							26,15,16	
- 1	1	хх	x x	3000	-1 .	Red / orange	6	
,						clay	16,25+,25+	
4	1	хх	x x	3000	-2 .	Red / orange	6	
1		A-20 W4				clay	25+,25+,25+	7
	1	x x	хх	3000	-3 .	Red / orange	6	T
1		0.041) >071)			-	clay	25+,25+,25+	7
	2	хх	хх	3000	0.	Red / orange	6	1
2						clay	9,8,9	7
	2	x x	x x	3000	-1 .	Red / orange	6	
2						 clay	25+,25+,25+	7
	2	x x	хх	3000	-2 .	Red / orange	6	
2						clay	11,14,25+	7
	2	хх	x x	3000	-3 .	Red / orange	- 6	
2		52 52	100 100			clay		7

By:	Eric Michael Barber, Jr.
	ECS Southeast, LLP



ECS Southeast, LLP

6151 Raeford Road Suite A Fayetteville, NC 28304 (910) 401-3288 [Phone] (910) 323-0539 [Fax]

Project

5311 Christian Light Road Foudation

Location

Fuquay- Varina, NC

Client

Carolina Builders Group - Accounts Payable

Remarks

Trip Charges*

Chargeable Items

Tolls/Parking*

Mileage*

Time of

Project No.

Report No.

Day & Date

On-Site Time

Travel Time*

Re Obs. Time

Weather

Lab Time

Total

Arrival

FIELD REPORT

33:4552

91°/ Cloudy

2.75

0.00

0.00

2.75

0.00

Departure

Monday 09/10/2018

08:45A 11:30A

* Travel time and mileage will be billed in accordance with the contract.

Summary of Services Performed (field test data, locations, elevations & depths are estimates) & Individuals Contacted.

An ECS representative arrived on site, as requested, to check the bearing capacity of soils via hand auger/dcp method for Christian Light Road Foundation. Please see the attached sketch.

A hand auger was used to advance the boreholes to different depths noted on the boring logs. Dynamic Cone Penetrometer (DCP) test were performed in the hand auger boreholes by a 1.5 inch diameter cone driven into the soil by a 15 pound ring weight with a free fall of 20 inches. The number of blows required to drive the cone into the soil a distance of 1.75 inches is termed the DCP Value and is indicated for each test on the hand auger.

A total of 5 hand auger/DCP evaluations were performed and did appear to be suitable to support the design bearing capacity of 3,000 psf.

The soil in place is suitable to support the structural, however some water was encountered therefore ECS recommends to remove 12 inches of the existing soil in the areas that are highlighted on the sketch. When the soil is removed ECS recommends to replace the soil with 57 stone or a similar wash stone back to the proposed grade, and to install a French drain at the rear side of the property to allow the water to drain away from the structure.

ECS will return, as requested, to perform additional services.



ECS Southeast, LLP

6151 Raeford Road Suite A Fayetteville, NC 28304 (910) 401-3288 [Phone] (910) 323-0539 [Fax]

LETTER OF TRANSMITTAL

September 11, 2018

Carolina Builders Group 4699 Hwy 87 S Sanford, NC 27332

ATTN: Accounts Payable

RE: 5311 Christian Light Road Foudation

ECS Job # 33:4552

Permits:

Location: 5311 Christian Light Road

Fuquay- Varina, NC

We are enclosing:

Field Reports

For your use

As requested X

ENCL:

Field Report # 1

09/10/2018

Dennis D Eowery, P0438 Project Engineer

Donny Johnson

Field Services Manager



ECS Southeast, LLP 6151 Raeford Road Suite A Fayetteville, NC 28304 (910) 401-3288 [Phone] (910) 323-0539 [Fax]

Project

5311 Christian Light Road Foudation

Location

Fuquay- Varina, NC

Client

Carolina Builders Group - Accounts Payable

Remarks

Trip Charges*

Chargeable Items

Tolls/Parking*

Mileage*

Time of

Total

Project No.

Report No.

Day & Date

On-Site Time

Travel Time*

Re Obs. Time

Weather

Lab Time

ne of Arrival

FIELD REPORT

1

2.75

0.00

0.00

2.75

33:4552

91°/ Cloudy

Monday 09/10/2018

08:45A 11:30A

Departure

* Travel time and mileage will be billed in accordance with the contract.

Summary of Services Performed (field test data, locations, elevations & depths are estimates) & Individuals Contacted.

An ECS representative arrived on site, as requested, to check the bearing capacity of soils via hand auger/dcp method for Christian Light Road Foundation. Please see the attached sketch.


A hand auger was used to advance the boreholes to different depths noted on the boring logs. Dynamic Cone Penetrometer (DCP) test were performed in the hand auger boreholes by a 1.5 inch diameter cone driven into the soil by a 15 pound ring weight with a free fall of 20 inches. The number of blows required to drive the cone into the soil a distance of 1.75 inches is termed the DCP Value and is indicated for each test on the hand auger.

A total of 5 hand auger/DCP evaluations were performed and did appear to be suitable to support the design bearing capacity of 3,000 psf.

The soil in place is suitable to support the structural, however some water was encountered therefore ECS recommends to remove 12 inches of the existing soil in the areas that are highlighted on the sketch. When the soil is removed ECS recommends to replace the soil with 57 stone or a similar wash stone back to the proposed grade, and to install a French drain at the rear side of the property to allow the water to drain away from the structure.

ECS will return, as requested, to perform additional services.

Christian Light Rd. Work: 47096 Project: 4552 Eric M. Barber Jr. 09-10-18



Legend (NTS) (CRAWLSPACE FOUNDATION PLAN

- Foundation evaluation (H)= DLP Location

CARDEINA BUILDERS
JOSE S. Harman Wart 8"(\$4) Sperfland, SrC. 2721Cl Advancement for any frequency or control of cont
AES DATE DESCRIPTION
8-
SIDENCE
1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1
CRAWLSPACE FOUNDATION PLAN
06/13/2018
1/8"=1"-0" U.N.O.
TE
TE181001



Project: 5311 Christian Light Road Foudation	Project No.	4552
Location: 5311 Christian Light Road Fuquay- Varina - Harnett County - NC - 27526	Day/Date:	09/10/18

Contractor: None Listed

		Size (V	V x H x L)	Footing Bott	om Elevation			Required Blow Counts	
Footing Number	Location	Design	Actual	Design	Depth of Undercut (in)	,	Description of Subgrade Material	# of Blows / increment	Design Bearing Pressure
1	1	хх	хх	3000	0 .		Red / clay		
								26,15,16	
1	1	x x	x x	3000	-1 .		Red / orange	6	
							clay	16,25+,25+	
1	1	x x	x x	3000	-2 .		Red / orange	6	
							clay	25+,25+,25+	1
1	1	x x	хх	3000	-3 .		Red / orange	6	
·							clay	25+,25+,25+	1
2	2	x x	хх	3000	0 .		Red / orange	6	
							clay	9,8,9	
2	2	x x	хх	3000	-1 .		Red / orange	6	
						a.	clay		1
2	2	x x	хх	3000	-2 .		Red / orange	6	
							clay	11,14,25+	
2	2	x x	хх	3000	-3 .		Red / orange	6	
							clay	15,18,19	1

Ву:	Eric Michael Barber, Jr.							
	ECS Southeast, LLP							



Project: 5311 Christian Light Road Foudation	Project No.	4552
Location: 5311 Christian Light Road	Day/Date:	09/10/18
Fuquay- Varina - Harnett County - NC - 27526		
Contractor: None Listed		

		Size (W x H x L)		Footing Bottom Elevation			Required Blow Counts	
Footing Number	Location	Design	Actual	Design	Depth of Undercut (in)	Description of Subgrade Material	# of Blows / increment	Design Bearing Pressure
3	3	хх	хх	3000	0 .	Red / orange sand	6 4.9,12	
3	3	x x	x x	3000	-1 .	Red / orange clay	6 8,12,12	
3	3	хх	хх	2000	-2 .	Red / orange	6 10,25+,25+	
3	3	x x	хх	3000	-3 .	Red / orange	6 11,25+,25+	
4	4	хх	хх	3000	0 .	Red / orange	6 3,4,7	
4	4	x x	хх	3000	-1 .	Red / orange	6 7,12,17	
4	4	x x	хх	3000	-2 .	Red / orange	6 HAR	
5	5	x x	хх	3000	0 .	Red / orange	6 6,7,11	

Ву:	Eric Michael Barber, Jr.					
	FCS Southeast LLP					



Project: 5311 Christian Light Road Foudation	Project No.	4552
Location: 5311 Christian Light Road Fuquay- Varina - Harnett County - NC - 27526	Day/Date:	09/10/18
Contractor: None Listed		

Size (W x H x L) Footing Bott		ttom Elevation			Required Blow Counts		
Footing Number	Location	Design	Actual	Design	Depth of Undercut (in)		Description of Subgrade Material	# of Blows / increment	Design Bearing Pressure
5	5	хх	хх	3000	-1 .		Red / orange	6	
								8,16,22	1
5	5	x x	x x	3000	-2 .		Red / orange	6	
								25+,25+,25+	1
5	5	x x	x x	3000	-3 .		Red / orange	6	
								HAR	1

Ву:	Eric Michael Barber, Jr.						
	ECS Southeast, LLP	_					

COUNTY OF HARNETT Building Inspections Department Planning Services Certificate of Compliance: Occupancy: Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following: **Permit Numbers CPSF** Use Classification: CPSF17-50042542 Robert J Tessier Building: Name: Electrical: 5311 Christian light road Insulation: Address: Fuguay-Varina, NC 27526 Plumbing: Mechanical: MFG Home: Building Official: (Date: 11-21-19

WILKINS ENGINEERING, P.C.

Post Office Box 37446 Raleigh, NC 27627

August 11, 2019

Mr. Peter Gitto AMG Realty, LLC 7320 Bassett Hall Ct. Raleigh, North Carolina

REFERENCE: 5311 Christian Light Road, Fuquay-Varina, NC Permit Number CPSF17-50042542

Dear Mr. Gitto:

I recently made a site visit to the above referenced location for the purpose of reviewing the most recent framing inspection. My findings and recommendations are outlined below.

The first item to be addressed is: "Need engineer repair for damaged floor trusses above kitchen and where trusses were damaged by termites". The damaged floor trusses were inspected and it appeared that there was minor termite damage but no active infestation. The damage was limited to the bottom chord of the trusses. In order to repair the damaged trusses I recommend the installation of a ½" OSB repair plate on one side of the truss from top chord to bottom chord. The plate should be nominally 48" long in order to cover more than one vertical and diagonal member of the truss. The repair plate should be attached with construction adhesive and nailed at 6" on center along the top and bottom chord and internal members. No other modification is required.

The second item to be addressed is: "Replace all short nails in truss hangers with 3-inch or provide engineering". I inspected the hanger installation to the main LVL that runs along the width of the structure and although they are not the short connectors manufactured by Simpson Strong-Tie they are structurally adequate to support the vertical reaction loads from the second floor trusses as well as pullout that could be realized. Accordingly, the nails as installed are structurally adequate.

The last item to be addressed is: "B2 trusses with scabbd boards require engineering or expose for inspection". The "B2" truss is a gable end truss that is intended to close off the ceiling/roof framing at a gable end. I thoroughly inspected this truss as well as reviewed the truss analysis and although additional lumber has been added, the truss is installed according to the erection plan and is structurally acceptable. No modification is required.

I hope you find this information useful. If you have any questions, or require additional information, please do not hesitate to contact me.

anald D Wills