

ADDRESS : 28 GLENSIDE CT SUBDIV: ANDERSON CREEK CLUB PH5E  
 CONTRACTOR : H & H CONSTRUCTORS INC PHONE : (910) 486-4864  
 OWNER : H & H CONSTRUCTORS INC PHONE :  
 PARCEL : 01-0535-23- -0100- -17-  
 APPL NUMBER: 17-50042554 CP NEW RESIDENTIAL (SFD)  
 DIRECTIONS : T/S: 10/13/2017 04:38 PM BPETRICH --  
 28 GLENSIDE COURT SPRING LAKE 28390  
 ANDERSON CREEK CLUB CARRIAGE GLEN #984

**STRUCTURE: 000 000 42X52 4BD 2.5BA SLAB W/GARAGE**

FLOOD ZONE : FLOOD ZONE X  
 # BATHS : 2.5 # BEDROOMS : 4.00  
 PROPOSED USE : SFD SEPTIC - EXISTING? : SEWER  
 WATER SUPPLY : COUNTY

**PERMIT: CPSF 00 CP \* SFD**

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
A814 01	12/06/17	SB	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 003062809
	12/06/17	AP	28 GLENSIDE CT SPRING LAKE 28390
			T/S: 12/06/2017 10:36 AM SBENNETT -----
B101 01	12/06/17	JH	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 003062791
	12/06/17	AP	T/S: 12/05/2017 01:59 PM BPETRICH -----
			TPOLE ALSO
B103 01	12/21/17	MC	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 003069358
	12/21/17	DA	T/S: 12/20/2017 09:39 AM BPETRICH -----
			T/S: 12/21/2017 03:17 PM MCOOK -----
			1. NEED RES-CHECK THAT IS ADDRESS SPECIFIC 2. NEED PORTA JOHN ON SITE
B103 02	12/22/17	MC	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 003070307
	12/22/17	AP	T/S: 12/21/2017 01:47 PM BPETRICH -----
			T/S: 12/22/2017 03:52 PM MCOOK -----
P309 01	1/24/18	JH	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 003079290
	1/24/18	AP	T/S: 01/23/2018 01:05 PM BPETRICH -----
B111 01	1/29/18	JH	R*BLDG SLAB INSP/TEMP SVC POLE TIME: 17:00 VRU #: 003081619
	1/29/18	DA	T/S: 01/26/2018 09:25 AM LLUCAS -----
			Remove water from lug footings
B111 02	2/01/18	JH	R*BLDG SLAB INSP/TEMP SVC POLE TIME: 17:00 VRU #: 003083672
	2/01/18	AP	T/S: 01/31/2018 11:34 AM LLUCAS -----
B104 01	3/07/18	LL	R*FOUND & SETBACK VERIF SURVEY TIME: 17:00 VRU #: 003098787
	3/07/18	AP	T/S: 03/07/2018 09:36 AM LLUCAS -----
			T/S: 03/07/2018 09:36 AM LLUCAS -----
R425 01	3/08/18	JH	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 003098795
	3/08/18	DA	T/S: 03/07/2018 09:36 AM LLUCAS -----
			1)Anchor interior load bearing walls per code.2)Nail all lvls every 12" per documents.3)Missing anchor bolts left side of garage,bay window walls in master bedroom & under window in living room.4)Hurricane straps for front & back porches need to be nail to beam.5)Need repair letter for split bottom cord in front right bedroom.6)Missing nails in hurricane straps throughout house.7)3' head of water on drain line test.8)Missing hurricane strap for 2ply truss in chase at top of stairs.

ADDRESS : 28 GLENSIDE CT  
 CONTRACTOR : H & H CONSTRUCTORS INC  
 OWNER : H & H CONSTRUCTORS INC  
 PARCEL : 01-0535-23- -0100- -17-  
 APPL NUMBER: 17-50042554 CP NEW RESIDENTIAL (SFD)

SUBDIV: ANDERSON CREEK CLUB PH5E  
 PHONE : (910) 486-4864  
 PHONE :

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
R425 02	3/20/18	JH	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 003103082
	3/20/18	AP	T/S: 03/19/2018 09:53 AM DJOHNSON -----
M305 01	4/18/18	JH	R*PLUMB SEWER CONNECTION TIME: 17:00 VRU #: 003115516
	4/18/18	AP	T/S: 04/17/2018 10:45 AM BPETRICH -----
P307 01	4/18/18	JH	R*PLUMB WATER CONNECTION TIME: 17:00 VRU #: 003115508
	4/18/18	AP	T/S: 04/17/2018 10:45 AM BPETRICH -----
I129 01	5/01/18	TSG	R*INSULATION INSPECTION TIME: 17:00 VRU #: 003120714
	5/01/18	AP	T/S: 04/30/2018 09:49 AM LLUCAS -----
			T/S: 05/01/2018 03:48 PM BPETRICH -----
R125 01	6/20/18	MC	ONE TRADE ROUGH IN TIME: 17:00 VRU #: 003141942
	6/20/18	AP	T/S: 06/19/2018 10:30 AM JBROCK -----
			stone inspection
			T/S: 06/20/2018 03:14 PM MCOOK -----
E209 01	6/21/18	JH	R*ELEC TEMP POWER CERT TIME: 17:00 VRU #: 003142759
	6/21/18	AP	T/S: 06/20/2018 11:37 AM JBROCK -----
R429 01	7/06/18	TSG	FOUR TRADE FINAL TIME: 17:00 VRU #: 003148137
	7/06/18	DA	T/S: 07/05/2018 09:40 AM BPETRICH -----
			T/S: 07/06/2018 03:26 PM LLUCAS -----
			<del>1.</del> INSTALL MECHANICAL <del>2.</del> MICROWAVE & VENT NOT INSTALLED
			<del>3.</del> NEED GARAGE DOOR WIND LOAD STICKER <del>4.</del> NO LADDER FOR ATTIC
			<del>5.</del> COULD NOT LOCATE ENERGY CERTIFICATE <del>6.</del> COULD NOT LOCATE
			DUCT PRESSURE TEST <del>7.</del> SEAL AND REPAIR A/C DUCT WALL AT FRONT
			DOOR <del>8.</del> SEAL AROUND ALL PIPE IN CABINETS
R429 02	7/10/18	TI	FOUR TRADE FINAL TIME: 17:00 VRU #: 003149291
	<u>7-10-18</u>	<u>APJA</u>	T/S: 07/09/2018 09:22 AM DJOHNSON -----

COMMENTS AND NOTES