Plan Box #<u>____</u>

Date 1/19/18	
Date// 0	
Job Name Breach INC	_
Plan Name3	_

App # 42991 Valuation 410,976

SQ Feet ______ Garage _____ = _____

Inspections for SFD/SFA

Crawl <u>V</u>	Slab	Mono	Basement
Footing	Footing	Plum Under Slab	Footing
Foundation	Foundation	Ele. Under Slab	Foundation
Address	Address	Address	Waterproofing
Open Floor	Slab	Mono Slab	Plum Under slab
Rough In	Rough In	Rough In	Address
Insulation	Insulation	Insulation	Slab
Final	Final	Final	Open Floor
			Rough In
			Insulation
			Final
Foundation Su	rvey_ <u>N</u> D Er	wir. Health <u>, N</u> CU) Other
Foundation Su	rvey <u>N</u> D Er	nvir. Health <u>, N</u> U) Other
Foundation Su	rvey <u>N</u> Er	nvir. Health <u>, N</u> EU	
Additions / Ot			
Additions / Ot Footing	<u>her</u>		
<u>Additions / Ot</u> Footing Foundation	<u>her</u>		
<u>Additions / Ot</u> Footing Foundation Slab	<u>her</u>		
Foundation Su Additions / Ot Footing Foundation Slab Mono Open Floor	<u>her</u>		

Insulation_____

Final_____