

ADDRESS : 199 GREEN LEVEL DR  
CONTRACTOR : CUMBERLAND HOMES INC  
OWNER : IOVINO JOHN MICHAEL  
PARCEL : 04-0663- - -0066- - -  
APPL NUMBER: 17-50042994 CP NEW RESIDENTIAL (SFD)  
DIRECTIONS : T/S: 12/22/2017 04:06 PM JBROCK ----  
MOUNTAIN LAUREL PLACE #54  
PREMISE#36220411  
EMAILED REQUEST TO DUKE - 3/27/18..LL

SUBDIV: NEILLS CREEK FARMS PHASE 1  
PHONE : (910) 892-4345  
PHONE :

STRUCTURE: 000 000 58X64 4BDR 2BA W/ GARAGE

FLOOD ZONE : FLOOD ZONE X  
# BATHS : 2  
PROPOSED USE : SFD  
WATER SUPPLY : COUNTY

# BEDROOMS : 4000000.00  
SEPTIC - EXISTING? : NEW TANK

PERMIT: CPSF 00 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	3/15/18	DT	R*BLDG FOOTING / TEMP SVC POLE VRU #: 003101904
	3/15/18	AP	T/S: 03/15/2018 12:45 PM DETAYLOR -----
B103 01	4/06/18	DT	R*BLDG FOUND & TEMP SVC POLE VRU #: 003111366
	4/06/18	AP	T/S: 04/06/2018 12:34 PM DETAYLOR -----
B111 01	4/17/18	DT	R*BLDG SLAB INSP/TEMP SVC POLE VRU #: 003114972
	4/17/18	DA	T/S: 04/17/2018 02:54 PM DETAYLOR ----- Was plumbing under slab inspection
A814 01	4/20/18	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 003116670
			T/S: 04/19/2018 12:37 PM DJOHNSON -----
B111 02	4/20/18	TI	R*BLDG SLAB INSP/TEMP SVC POLE TIME: 17:00 VRU #: 003116662
	4/20/18	AP	T/S: 04/19/2018 12:37 PM DJOHNSON -----

COMMENTS AND NOTES

Joe E Godwin Sr. , P.E., P.L.S.

Fleet Temple , P.E.

Jason E Godwin , P.L.S.

# ENOCH ENGINEERS, P.A.

1403 NC Highway 50 South  
Benson, North Carolina 27504  
919.894.7765

Email: [general@enochengineers.com](mailto:general@enochengineers.com)

[www.enochengineers.com](http://www.enochengineers.com)

## MATERIALS & TEST DIVISION

### FIELD REPORT

#### PROJECT

CLIENT: Cumberland Homes	DATE: 4.19.18
PROJECT: Neills Creek Farms s/d	CONTRACTOR: c/o Dennis Norris
ADDRESS: 39 Mountain Laurel Place	TECHNICIAN: TW
LOT #: 54	

#### TEST SUMMARY

Performed NDT on pad site noted above using a target density of 99 PCF. Soils confirmed a compaction greater than or equal to 95%.

#### TESTING RESULTS

SERVICE PERFORMED	TEST NO.	COMP %	WD PCF	DD PCF	MOISTURE %
NDT	1	97.4	118.3	96.4	22.8

#### RETURN VISIT REQUIRED?

YES

NO

TECHNICIAN:

Disclaimer:

Soils & Material Inspections, testing results and on-site determinations contained in this report become void after 60 days of non-use of this report and/or following any inclement weather which causes structural soil or material deterioration. Additional testing will be required following a voided report determined by a North Carolina Building Code enforcement official or Enoch Engineers P.A. The client/contractor is responsible for notifying Enoch Engineers P.A. of any soil & material condition changes which could void this report.