



Harnett County
 108 EAST FRONT STREET
 LILLINGTON, NC 27546
 Phone:
 Fax:

8/21/2019

**SUBJECT: CPSF18-50043216
 BUILDING RESIDENTIAL**

To:

Here are the results of all Inspections located at **830 TRUELOVE RD:**

Inspection Type: FINAL SFD CRAWL**
 Scheduled Date/Time:
 Completed Date/Time:
 Inspector: Brad Sutton
 Result:
 Remarks:
 Notes:

Inspection Type: ENVIR. HLTH. CONFIRMATION
 Scheduled Date/Time: 2/16/2018
 Completed Date/Time: 2/15/2018
 Inspector: Unassigned
 Result: APPROVED
 Remarks:
 Notes: T/S: 02/16/2018 11:39 AM KHINSON -----

Inspection Type: ADDRESS CONFIRMATION
 Scheduled Date/Time: 2/26/2018
 Completed Date/Time: 2/27/2018
 Inspector: Unassigned
 Result: APPROVED
 Remarks:
 Notes: 830 TRUELOVE RD HOLLY SPRINGS 27540
 T/S: 02/27/2018 09:03 AM SBENNETT -----

Inspection Type: R BLDG FOOTING / TEMP SVC POLE
 Scheduled Date/Time: 7/12/2018
 Completed Date/Time: 7/12/2018
 Inspector: Unassigned
 Result: APPROVED
 Remarks:
 Notes: T/S: 07/11/2018 10:23 AM LLUCAS -----
 T/S: July 12, 2018 03:24 PM BSUTTON -----





Harnett County
108 EAST FRONT STREET
LILLINGTON, NC 27546
Phone:
Fax:

Inspection Type: FOUNDATION
Scheduled Date/Time: 8/7/2018
Completed Date/Time: 8/7/2018
Inspector: Mike Cook
Result: APPROVED
Remarks:
Notes: 1. No dampproofing install at this time

Inspection Type: T-POLE
Scheduled Date/Time: 10/30/2018
Completed Date/Time: 10/30/2018
Inspector: Scott Guy
Result: APPROVED
Remarks:
Notes:

Inspection Type: OPEN FLOOR
Scheduled Date/Time: 1/14/2019
Completed Date/Time: 1/14/2019
Inspector: Brad Sutton
Result: APPROVED
Remarks:
Notes:

Inspection Type: ROUGH IN SFD CRAWL
Scheduled Date/Time: 3/29/2019
Completed Date/Time: 3/29/2019
Inspector: Deen Taylor
Result: DISAPPROVED
Remarks:
Notes: 1. Install 2 inch washers for bolts at garage wing walls. 2. Plywood must be on both sides of floor joist where 3 inch line passes. OK to side and insulate

Inspection Type: INSULATION
Scheduled Date/Time: 4/10/2019
Completed Date/Time: 4/10/2019
Inspector: Ray Holder
Result: DISAPPROVED
Remarks:
Notes: Can not complete insulation inspection until rough in inspection passes. Items on rough in inspection not done.





Harnett County
108 EAST FRONT STREET
LILLINGTON, NC 27546
Phone:
Fax:

Inspection Type: INSULATION
Scheduled Date/Time: 4/18/2019
Completed Date/Time: 4/18/2019
Inspector: Ray Holder
Result: APPROVED
Remarks:
Notes:

Inspection Type: ROUGH IN SFD CRAWL
Scheduled Date/Time: 4/29/2019
Completed Date/Time: 4/29/2019
Inspector: Deen Taylor
Result: APPROVED
Remarks:
Notes:

Inspection Type: ENVIR OPERATIONS PERMIT
Scheduled Date/Time: 6/24/2019
Completed Date/Time: 7/25/2019
Inspector: Andrew Currin
Result: APPROVED
Remarks:
Notes: Power access pending. Shall be routed down pl, driveway, and house box
Access verified

Inspection Type: SEWER CONNECTION
Scheduled Date/Time: 6/27/2019
Completed Date/Time: 6/27/2019
Inspector: Deen Taylor
Result: APPROVED
Remarks:
Notes: Approved this date per Deen Taylor.

Inspection Type: WATER CONNECTION
Scheduled Date/Time: 6/27/2019
Completed Date/Time: 6/27/2019
Inspector: Deen Taylor
Result: APPROVED
Remarks:
Notes:



Harnett County
108 EAST FRONT STREET

LILLINGTON, NC 27546

Phone:

Fax:

Inspection Type: FINAL SFD CRAWL**

Scheduled Date/Time: 8/19/2019

Completed Date/Time: 8/19/2019

Inspector: Deen Taylor

Result: DISAPPROVED

Remarks:

Notes:

Complete energy efficiency certificate and redo garage steps ensuring riser heights are uniform OK for power