PREPARED 6/27/18, 14:05:38 INSPECTION TICKET 30 PAGE DATE 6/28/18 Harnett County INSPECTOR: IVR ADDRESS . : 562 NEW CASTLE LN SUBDIV: HIGHGROVE@ANDERSON CRK 6B 39LO

PHONE : (910) 486-4864 CONTRACTOR : H & H CONSTRUCTORS INC

OWNER . . : H & H CONSTRUCTORS INC PHONE :

PARCEL . .: 01-0504-02- -0177- -53-

APPL NUMBER: 18-50043702 CP NEW RESIDENTIAL (SFD) DIRECTIONS: T/S: 04/03/2018 09:44 AM BPETRICH --

562 NEW CASTLE LANE SPRING LAKE 28390 HIGHGROVE @ ANDERSON CREEK #209

STRUCTURE: 000 000 40X41 3BD 2.5BA CRAWL W/GARAGE & PATIO

FLOOD ZONE . . . : FLOOD ZONE X

BEDROOMS : 3.00

BEDROOMS :
SEPTIC - EXISTING? : SEWER

3 THE STATE OF THE

WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
A814 01	6/26/18	SB	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 003144300
	6/26/18	AP	562 NEW CASTLE LN SPRING LAKE 28390 T/S: 06/26/2018 04:37 PM SBENNETT
B101 01	6/26/18	JH	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 003144292
	6/26/18	DA	T/S: 06/25/2018 12:46 PM BPETRICH waiting on engineer letter
B101 02	6-28/18	APTH	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 003144979 T/S: 06/26/2018 01:32 PM BPETRICH T/S: 06/27/2018 08:48 AM LLUCAS

----- COMMENTS AND NOTES ------



06/26/2018

H & H Homes 2919 Breezewood Avenue Suite 400 Fayetteville, NC 28303

Attention : Calvin King John Rice

RE: Daily Field Report for 06/26/2018

Lot 209 Highgrove HGR (CMT) Spring Lake, NC

Building & Earth Project No: RD180331

Ladies and Gentlemen:

On this date, representative(s) of Building & Earth were present to perform construction material testing services at this project site. Our testing and observations for this date include the following:

FO-2: Field Observations made on this date.
• Repairs to Lot 209 Highgrove

Passed

Closing

The testing and observations identified above have been reviewed by our project manager. If you have questions regarding this information, please do not hesitate to contact us.

Respectfully Submitted, Building & Earth Sciences, LLP

Enclosures: FO-2



610 Spring Branch Road Dunn, NC 28334 Phone 910-292-2085 Fax 910-292-2192 www.BuildingandEarth.com Rachael Heath



Field Observations Report

Project Name:

Lot 209 Highgrove HGR (CMT) Spring Lake, Project Number:

RD180331

Client Name:

H & H Homes

Placement#:

FO-2

Contractor:

Technician:

Rachael Heath

Monitoring:

Repairs to Lot 209 Highgrove

Passed

Based upon our observations, the recommended repairs have been accomplished, bearing capacity of 2,000 psf is available and the building pad is now acceptable for the placement of concrete. See attached photos.

Additionally, inclement weather (rain or snow), as well as construction traffic across the pad, can compromise the stability and support characteristics of the surface soils. If the surface soils become compromised, it will be necessary to return to the site for re-testing. This decision should be executed by your onsite Quality Control and Superintendents.



Field Observations Report

Project Name:

Lot 209 Highgrove HGR (CMT) Spring Lake, Project Number:

RD180331

Client Name:

H & H Homes

Placement#:

FO-2


Contractor:


Technician:

Rachael Heath

Monitoring:

Photographs





610 Spring Branch Road Dunn, NC 28334 Phone 910-292-2085 Fax 910-292-2192 www.BuildingandEarth.com

Rachael Heath