

ADDRESS : 70 ALVIS CT SUBDIV: DEXTERFIELD  
CONTRACTOR : SIGNATURE HOME BUILDERS PHONE : (910) 892-9299  
OWNER : CAPE FEAR BUILDERS & KEITH & M PHONE :  
PARCEL : 08-0653- - -0030- -48-  
APPL NUMBER: 18-50043948 CP NEW RESIDENTIAL (SFD)  
DIRECTIONS : T/S: 05/07/2018 10:52 AM JBROCK ----  
DEXTERFIELD #48  
ALVIS CT

STRUCTURE: 000 000 48X53 4BDR 2.5BA SLAB W/GARAGE

FLOOD ZONE : FLOOD ZONE X  
# BATHS : 2.5 # BEDROOMS : 4.00  
PROPOSED USE : SFD SEPTIC - EXISTING? : NEW TANK  
WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
A814 01	6/07/18	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 003136249 T/S: 06/06/2018 08:52 AM LLUCAS -----
B101 01	6/08/18 <u>G-8</u>	TI <u>AP</u>	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 003136256 T/S: 06/06/2018 08:52 AM LLUCAS ----- PLZ CHECK T-POLE ALSO :) T/S: 06/06/2018 03:01 PM JBROCK -----

COMMENTS AND NOTES

905 46424  
called @ 1005

Joe E Godwin Sr. , P.E., P.L.S.

Fleet Temple , P.E.

Jason E Godwin , P.L.S.

# ENOCH ENGINEERS, P.A.

1403 NC Highway 50 South  
Benson, North Carolina 27504  
919.894.7765

Email: [general@enochengineers.com](mailto:general@enochengineers.com)

[www.enochengineers.com](http://www.enochengineers.com)

## MATERIALS & TEST DIVISION

### FIELD REPORT

#### PROJECT

CLIENT: <b>Signature Home Builders</b>	DATE: <b>6.8.18</b>
PROJECT: <b>resi</b>	CONTRACTOR: <b>c/o Chris Sherrod</b>
ADDRESS: <b>70 Alvit Ct.</b>	TECHNICIAN: <b>BH</b>
LOT #: <b>48</b>	

#### TEST SUMMARY


Performed footing inspection at site noted above. Soils confirmed a minimum allowable bearing capacity of 2000 LBS PSF.  
Recommended backfilling with washed #57 stone to grade.

#### TESTING RESULTS

SERVICE PERFORMED	TEST NO.	COMP %	WD PCF	DD PCF	MOISTURE %

#### RETURN VISIT REQUIRED?

YES   
NO

TECHNICIAN: 

Disclaimer:

Soils & Material inspections, testing results and on-site determinations contained in this report become void after 60 days of non-use of this report and/or following any inclement weather which causes structural soil or material deterioration. Additional testing will be required following a voided report determined by a North Carolina Building Code enforcement official or Enoch Engineers P.A. The client/contractor is responsible for notifying Enoch Engineers P.A. of any soil & material condition changes which could void this report.