		Date	10/5/18	
Plan Box #	33	Job Name	Bellock	
,		Plan Name_		
			* .	
App #	100	Valuation 131,904	SQ Feet_	1374
-PP ''			Garage	519
			- Curuge	1093
				(0/)
Inspections for	CED/CEA			
Inspections for	<u> SFUJSFA</u>		8 · K	
Crawl	Slab	Mono	Basement	
Footing	Footing	Plum Under Slab	Footing	
Foundation	Foundation	Ele. Under Slab	Foundation	
Address	Address	Address	Waterproofing	
Open Floor	Slab	Mono Slab	Plum Under slab	
Rough In	Rough In	Rough In	Address	
Insulation	Insulation	Insulation	Slab	
Final	Final	Final	Open Floor	
		•	Rough In	
			Insulation	
			Final	
Foundation Surve	ey	Envir. Health	Other	
	× ×			
• • • • • • • • • • • • • • • • • • • •	•••••			
Additions / Other				
Footing				
Foundation				
Slab				
Mono			,	
			· · · · · · · · · · · · · · · · · · ·	
Open Floor				• 1
Rough In				
nsulation				
-ınai				

그리 말라면서 그리는 다양 빛수하다니?			
	348		