

Plan Box # File

Date 1/25/18

Job Name Tarheel Restoration, Inc

Plan Name _____

App # 43160

Valuation \$ 33,576

SQ Feet 204 - 19584
Patio
Garage 372 - 13992
= 576

Inspections for SFD/SFA

Crawl _____ Slab _____ Mono _____ Basement _____

| | | | |
|------------|------------|-----------------|-----------------|
| Footing | Footing | Plum Under Slab | Footing |
| Foundation | Foundation | Ele. Under Slab | Foundation |
| Address | Address | Address | Waterproofing |
| Open Floor | Slab | Mono Slab | Plum Under slab |
| Rough In | Rough In | Rough In | Address |
| Insulation | Insulation | Insulation | Slab |
| Final | Final | Final | Open Floor |
| | | | Rough In |
| | | | Insulation |
| | | | Final |

Foundation Survey NO Envir. Health exist Other _____

Additions / Other

Footing _____
Foundation _____
Slab _____
Mono _____
Open Floor _____
Rough In _____
Insulation _____
Final _____

24x24 Pool House