HTE# 18-5-43401

ENVIRONMENTAL HEALTH 307 CORNELIUS HARNETT BOULEVARD LILLINGTON, NC 27546

EDTIC SYSTEM INSPECTION

	EXISTING SEPTICS	131EM HASTECTION
NAME Fno	ed WADE	PHONE # 919 820-6335
ADDRESS 5	89 W TANT PUB	DUAN NIC 28534
NAME OF MO	BILE HOME PARK OR S/D _	
NAME OF OW	NER (IF DIFFERENT)	
ADDRESS OF	OWNER (IF DIFFERENT)	
PROPERTY LO	OCATION: STATE ROAD NA	ME AND # SN 2060 W TANT PA
PURPOSE	OF INSPECTION: ZYYZY	leport AND to Brack Bow
The aforemen	itioned site has been evaluate	d by the Harnett County Health Department of inspection, there appeared to be a septic
system servin	githis site. If this system shou any:necess	ild malfunction, the owner is responsible for
	any lieuess	at transmission of the second
	TION IS VOID IF:	
	l use of the septic system should hould fail or malfunction, and/o	

- (3) the owner or tenant of the property changes, and/or
- (4) after six months

Control of the control of

told it was the same
3-9-18
Date