PREPARED 2/21/18, 15:15:54 Hårnett County INSPECTION TICKET

INSPECTOR: IVR

PAGE DATE

2/22/18

ADDRESS . : 174 SCHOLAR DR

SUBDIV:

CONTRACTOR : ANDERSON CREEK DEVELOPERS LLC

PHONE: (910) 814-2633

OWNER . . : ANDERSON CREEK PARTNERS LP

PARCEL . . : 01-0535-25- -0100- -52-

APPL NUMBER: 17-50040593 CP NEW COMMERCIAL BLDG/ENTERPRISE

DIRECTIONS: T/S: 01/20/2017 09:48 AM DJOHNSON --

TAKE RAY RD TO LEFT ON ANDERSON CREEK DR, RIGHT ON BARONS RUN E, RIGHT ON WHISPERING PINES DR, RIGHT ON ANDERSON LAKE DR, RIGHT ON SCHOLAR DR, LOCATION

300 FT ON RIGHT.

STRUCTURE: 000 000 75X35 EXERCISE FACILITY/POOL HOUSE

FLOOD ZONE . . . : FLOOD ZONE X

PROPOSED USE . . . . . : EX FAC./ PL HSE SEPTIC - EXISTING? . . . : SEWER

\_\_\_\_\_\_ PERMIT: CBCO 00 CP BUILDING COMMERCIAL REQUESTED INSP DESCRIPTION RESULTS/COMMENTS TYP/SO COMPLETED RESULT \_\_\_\_ ADDRESS CONFIRMATION TIME: 17:00 VRU #: 003048949 A814 0.1 11/03/17 SB 11/03/17 AΡ 174 SCHOLAR DR SPRING LAKE 28390 T/S: 11/03/2017 11:32 AM SBENNETT ------C\*BLDG FOOTING TIME: 17:00 VRU #: 003048931 C151 01 11/03/17 TSG T/S: 11/02/2017 01:28 PM BPETRICH ------11/03/17 DA not ready C151 02 JH C\*BLDG FOOTING TIME: 17:00 VRU #: 003049889 11/06/17 T/S: 11/03/2017 04:24 PM DJOHNSON ------11/06/17 DΑ Footing in breezeway doesn.t match plans & slab insulation needs to be 8" from bottom of footings 11/07/17 JΗ C\*MONOLITH SLAB TIME: 17:00 VRU #: 003050671 C161 01 T/S: 11/07/2017 11:36 AM DJOHNSON ------11/07/17 AΡ T/S: 11/07/2017 11:36 AM DJOHNSON -----C153 01 2/09/18 JΗ C\*BLDG ROUGH IN TIME: 17:00 VRU #: 003087517 T/S: 02/08/2018 01:59 PM JBROCK ------2/09/18 DA 1) Replace over notched stud to left of door for womens bathroom & in mechanical room in corner.2) Anchor bolt at womens bath sink.3) Need chase for 3" pipe in chemical room & fire caulk top of chase.4) Missing hurricane straps on front & back porches.5) Fire caulk hole in top plate in gym room on right wall. C\*BLDG ROUGH IN TIME: 17:00 VRU #: 003087897 C153 02 2/12/18 JΗ AΡ T/S: 02/09/2018 11:47 AM JBROCK ------2/12/18 2/22/18 2-22-18 AP C\*BLDG FOOTING TIME: 17:00 VRU #: 003092954 C151 03 T/S: 02/21/2018 03:13 PM DJOHNSON ------TWO FOOTINGS NEED TO BE INSPECTED FOR THE PERGOLA PER ERIC.

HE SAID ENGINEER LETTERS ARE ON SITE

------ COMMENTS AND NOTES ---------

## DAVID MILLER, PE

6300 Creedmoor Rd, STE 170#363 Raleigh, NC 27612 (919) 422-8932 (Office); <u>DAVE@DMA-PA.COM</u>

February 20,2018

Anderson Creek Partners LP Attn.: Andy Barr 919-454-4680 Anderson Creek, NC

E-mailed: andybarr40@yahoo.com

RE: Engineering -Structural Academy Swim Club Anderson Creek Lillington, NC Project No.:17DDM-1103A2

To whom it may concern/Inspections Dept.:

The two footings analyzed are 2ftx2ftx2ft. On top are 6x6's with brackets a (2) - 2x10 header. The top of the pergola is to be 2x8's approximately 12' long that will ledger to the double 2x8 beam that runs across the front porch and sit on the (2) - 2x10 header. The two footings are adequate to support the vertical compressive and uplift loading conditions transferred through the framed system outlined. Sincerely,

David Miller, PE

DEM/17DDM-1103A2

