

APPLICANT NAME _____

DATE _____

FACTORS		PROFILES								
		1	2	3	4	5	6	7	8	9
LANDSCAPE POSITION	.1940									
SLOPE (%)	.1940									
HORIZON 1 DEPTH		0-4	0-42	0-40						
Texture Group	.1941(A)(1)	cl/c	cl/c	cl/c						
Consistence	.1941									
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
HORIZON 2 DEPTH		4-34								
Texture Group	.1941(A)(1)	cl/sc								
Consistence	.1941	F								
Structure	.1941(A)(2)	SB/c								
Mineralogy	.1941(A)(3)	SEP								
HORIZON 3 DEPTH		34-48								
Texture Group	.1941(A)(1)	cl/sc								
Consistence	.1941									
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
HORIZON 4 DEPTH										
Texture Group	.1941(A)(1)									
Consistence	.1941									
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
SOIL WETNESS	.1942	—	—	—						
RESTRICTIVE HORIZON	.1944									
SAPROLITE	.1943/1956									
CLASSIFICATION	.1948	PS	PS	PS						
LONG TERM ACCEPTANCE RATE	.1955	.6	.8	.8						

20 Nov 2000 need to meet Mr. Yates on-site for cleaning