

APPLICANT NAME \_\_\_\_\_

DATE \_\_\_\_\_

FACTORS		PROFILES								
		1	2	3	4	5	6	7	8	9
LANDSCAPE POSITION	.1940	L	L	L						
SLOPE (%)	.1940	2	2	2						
HORIZON 1 DEPTH		0-12	0-10	0-12						
Texture Group	.1941(A)(1)	SL	SL	SL						
Consistence	.1941	PK	PK	PK						
Structure	.1941(A)(2)	GR	GR	GR						
Mineralogy	.1941(A)(3)	NSNP	NSNP	NSNP						
HORIZON 2 DEPTH		12-20	10-20	12-20						
Texture Group	.1941(A)(1)	SL	SL	SL						
Consistence	.1941	PK	PK	PK						
Structure	.1941(A)(2)	GR	GR	GR						
Mineralogy	.1941(A)(3)	SSSP	SSSP	SSSP						
HORIZON 3 DEPTH		20-30	20-36	20-36						
Texture Group	.1941(A)(1)	SC CL	SC CL	SC CL						
Consistence	.1941	PK	PK	PK						
Structure	.1941(A)(2)	PAK	PAK	PAK						
Mineralogy	.1941(A)(3)	SSSP	SSSP	SSSP						
HORIZON 4 DEPTH										
Texture Group	.1941(A)(1)									
Consistence	.1941									
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
SOIL WETNESS	.1942	32	30	32						
RESTRICTIVE HORIZON	.1944									
SAPROLITE	.1943/1956									
CLASSIFICATION	.1948	PS	PS	PS						
LONG TERM ACCEPTANCE RATE	.1955	.4	.4	.4						

NO Repair needed  
IN CAPTAINS LANDING