


# SITE/SOIL EVALUATION FOR ON-SITE STEWATER

APPLICANT NAME \_\_\_\_\_

DATE \_\_\_\_\_

FACTORS		PROFILES													
		1	2	3	4	5	6	7	8	9	10				
LANDSCAPE POSITION	.1940														
SLOPE (%)	.1940														
HORIZON 1 DEPTH		c-8	c-12	o-8	o-6										
Texture Group	.1941(A)(1)	SL	SL	SL	SL										
Consistence	.1941	Vhr	Vhr	Vhr	Vhr										
Structure	.1941(A)(2)	G	G	G	G										
Mineralogy	.1941(A)(3)	Nod	Nod	Nod	Nod										
HORIZON 2 DEPTH		8-30	12-30	8-24	6-36										
Texture Group	.1941(A)(1)	SC1	SC1	SC	SL										
Consistence	.1941	F	F	K	K										
Structure	.1941(A)(2)	SBK	SBK	SBK	SBK										
Mineralogy	.1941(A)(3)	SOV	SOV	SOV	SOV										
HORIZON 3 DEPTH															
Texture Group	.1941(A)(1)														
Consistence	.1941														
Structure	.1941(A)(2)														
Mineralogy	.1941(A)(3)														
HORIZON 4 DEPTH															
Texture Group	.1941(A)(1)														
Consistence	.1941														
Structure	.1941(A)(2)														
Mineralogy	.1941(A)(3)														
SOIL WETNESS	.1942	28"		24"											
RESTRICTIVE HORIZON	.1944														
SAPROLITE	.1943/.1956														
CLASSIFICATION	.1948	PS	PS	WPS	PS										
LONG TERM ACCEPTANCE RATE	.1955	.3	.3	.3	.8										





4x75  
 18" mat  
 12" lat


PLATE PLAN APPROVAL

DISTRICT RA 30 USE SFD

#BEDROOMS 3

2/8/01

*J. Messersmith*  
Zoning Administrator



Lot 20 Donnibrook

Required Property Line Setbacks

	Minimum	Actual
Front	35	50
Side	10	16.75
Corner	20	-
Rear	25	150
Nearest Building	10	-

← Donnibrook Run →

1 inch = 40 feet