


SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

APPLICANT NAME _____

DATE _____

FACTORS		PROFILES													
		1	2	3	4	5	6	7	8	9	10				
LANDSCAPE POSITION	.1940														
SLOPE (%)	.1940														
HORIZON 1 DEPTH		0-12	0-8	0-8	0-8	0-24	0-16	0-4	0-30						
Texture Group	.1941(A)(1)	CS	LS	LS	LS	LS	LS	LS	LS						
Consistence	.1941														
Structure	.1941(A)(2)														
Mineralogy	.1941(A)(3)														
HORIZON 2 DEPTH		12-26	8-24	8-18	8-18	21-30	16-32	11-18	30-42						
Texture Group	.1941(A)(1)	SC	SC	SL	SL	PM	SC	SL	SC						
Consistence	.1941						EXP	EXP							
Structure	.1941(A)(2)														
Mineralogy	.1941(A)(3)														
HORIZON 3 DEPTH		26-32	24-30	18-24	18-24										
Texture Group	.1941(A)(1)	SC	SC	SL	SL										
Consistence	.1941			EXP	EXP										
Structure	.1941(A)(2)														
Mineralogy	.1941(A)(3)														
HORIZON 4 DEPTH		32-Rck	30-Rck												
Texture Group	.1941(A)(1)														
Consistence	.1941														
Structure	.1941(A)(2)														
Mineralogy	.1941(A)(3)														
SOIL WETNESS	.1942														
RESTRICTIVE HORIZON	.1944														
SAPROLITE	.1943/.1956														
CLASSIFICATION	.1948	PS	PS	US	US	US	US	US	PS						
LONG TERM ACCEPTANCE RATE	.1955	.3	.3	W	W	W	W	W	.6						

Overall
Dang




LEGEND:
 EIP - EXISTING IRON PIN/PIPE
 SIP - SET IRON PIN
 ECM - EXISTING CONCRETE MONUMENT
 R/W - RIGHT OF WAY
 DB - DEED BOOK
 PB - PLAT BOOK
 PG - PAGE

Required Property Line Setbacks

	Required	Actual
Front	35	60
Side	10	36
Corner	20	65
Rear	25	60
Nearest Building	10	

Vicinity Map
(Not to Scale)

Plat 99/86B



TE PLAN APPROVAL
 DISTRICT BAAB USE SFD
 #BEDROOMS 3
 Zoning Administrator

- NOTES:**
- 1) THERE ARE NO ENCROACHMENTS ACROSS PROPERTY LINE EXCEPT AS SHOWN ON MAP.
 - 2) SUBJECT PROPERTY IS NOT LOCATED IN A SPECIAL FLOOD HAZARD AREA.

PLOT PLAN