

SITE SOIL EVALUATION FOR ON-SITE WASTEWATER


APPLICANT NAME _____

DATE _____

FACTORS		PROFILES									
		1	2	3	4	5	6	7	8	9	10
LANDSCAPE POSITION	.1940										
SLOPE (%)	.1940										
HORIZON 1 DEPTH		0-18									
Texture Group	.1941(A)(1)	LS									
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
HORIZON 2 DEPTH		18-38									
Texture Group	.1941(A)(1)	SCC									
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
HORIZON 3 DEPTH		38-48									
Texture Group	.1941(A)(1)	CL Lm									
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
HORIZON 4 DEPTH											
Texture Group	.1941(A)(1)										
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
SOIL WETNESS	.1942										
RESTRICTIVE HORIZON	.1944										
SAPROLITE	.1943/1956										
CLASSIFICATION	.1948										
LONG TERM ACCEPTANCE RATE	.1955	.5									

1 X 240
18-24

1"=40'
Yonkers
Lot 107



Lot 107
1 X 2 1/2
18-24

MANHATTAN
5' to 10' of front
5' to 10' on all sides
Dr. Pump well
Be Resurfaced

PLAN APPROVAL
DISTRICT RA20R USE SFD
#BEDROOMS 3

2/28/01
Theresa Jones
Zoning Administrator

Required Property Line Setbacks

	Minimum	Actual
Front	35	45
Side	10	51
Corner	20	21
Rear	25	27
Nearest Building	10	11