

# SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

APPLICANT NAME \_\_\_\_\_

DATE \_\_\_\_\_

FACTORS		PROFILES												
		1	2	3	4	5	6	7	8	9	10			
LANDSCAPE POSITION	.1940													
SLOPE (%)	.1940													
HORIZON 1 DEPTH		0-16	0-18	0-16										
Texture Group	.1941(A)(1)	SL	SL	SL										
Consistence	.1941	Vr	Vs	Vr										
Structure	.1941(A)(2)	G	G	G										
Mineralogy	.1941(A)(3)	NCH	NCH	NCH										
HORIZON 2 DEPTH		16-32	18-72	16-32										
Texture Group	.1941(A)(1)	SL	SL	SL										
Consistence	.1941	F	Vr	L										
Structure	.1941(A)(2)	SBK	SBK	SBK										
Mineralogy	.1941(A)(3)	SEX	SCA	SEW										
HORIZON 3 DEPTH														
Texture Group	.1941(A)(1)													
Consistence	.1941													
Structure	.1941(A)(2)													
Mineralogy	.1941(A)(3)													
HORIZON 4 DEPTH														
Texture Group	.1941(A)(1)													
Consistence	.1941													
Structure	.1941(A)(2)													
Mineralogy	.1941(A)(3)													
SOIL WETNESS	.1942													
RESTRICTIVE HORIZON	.1944													
SAPROLITE	.1943/1956													
CLASSIFICATION	.1948	PJ	PI	PJ										
LONG TERM ACCEPTANCE RATE	.1955	.4	.4	.4										

