

# SITE/S... EVALUATION FOR ON-SIT WASTEWATER

APPLICANT NAME \_\_\_\_\_

DATE \_\_\_\_\_

FACTORS		PROFILES													
		1	2	3	4	5	6	7	8	9	10				
LANDSCAPE POSITION	.1940														
SLOPE (%)	.1940														
HORIZON 1 DEPTH		0-26	0-40	0-40	0-30	0-30									
Texture Group	.1941(A)(1)	LJ	LJ	LJ	LJ	LJ									
Consistence	.1941	VFr	VFr	VFr	VFr	VFr									
Structure	.1941(A)(2)	<del>SCL</del>	G	G	G	G									
Mineralogy	.1941(A)(3)	SCL	Nsp	Nsp	Nsp	Nsp									
HORIZON 2 DEPTH		2-45			20-2	20-26									
Texture Group	.1941(A)(1)	SCL			SCL	SK									
Consistence	.1941	Fr			Fr	VFr									
Structure	.1941(A)(2)	SCL			SCL	G									
Mineralogy	.1941(A)(3)	SCL			SCL	Nsp									
HORIZON 3 DEPTH															
Texture Group	.1941(A)(1)					SK									
Consistence	.1941					Fr									
Structure	.1941(A)(2)					SCL									
Mineralogy	.1941(A)(3)					SCL									
HORIZON 4 DEPTH															
Texture Group	.1941(A)(1)														
Consistence	.1941														
Structure	.1941(A)(2)														
Mineralogy	.1941(A)(3)														
SOIL WETNESS	.1942														
RESTRICTIVE HORIZON	.1944														
SAPROLITE	.1943/1956														
CLASSIFICATION	.1948	.P	5	5	PS	PS									
LONG TERM ACCEPTANCE RATE	.1955	.6	.8	.8	.4	.5									

