

SITE/SUB-EVALUATION FOR ON-SIT WASTEWATER

APPLICANT NAME _____

DATE _____

FACTORS		PROFILES												
		1	2	3	4	5	6	7	8	9	10			
LANDSCAPE POSITION	.1940													
SLOPE (%)	.1940													
HORIZON 1 DEPTH		2.48												
Texture Group	.1941(A)(1)	SCL												
Consistence	.1941													
Structure	.1941(A)(2)													
Mineralogy	.1941(A)(3)													
HORIZON 2 DEPTH														
Texture Group	.1941(A)(1)													
Consistence	.1941													
Structure	.1941(A)(2)													
Mineralogy	.1941(A)(3)													
HORIZON 3 DEPTH														
Texture Group	.1941(A)(1)													
Consistence	.1941													
Structure	.1941(A)(2)													
Mineralogy	.1941(A)(3)													
HORIZON 4 DEPTH														
Texture Group	.1941(A)(1)													
Consistence	.1941													
Structure	.1941(A)(2)													
Mineralogy	.1941(A)(3)													
SOIL WETNESS	.1942													
RESTRICTIVE HORIZON	.1944													
SAPROLITE	.1943/1956													
CLASSIFICATION	.1948													
LONG TERM ACCEPTANCE RATE	.1955	.5												

$\frac{720}{5} = 144$
 $\frac{360}{3} = 120$
 $\frac{240}{2} = 120$
 $\frac{360}{3} = 120$

LMAR = .5
 1 x 2 to 18-20

SITE PLAN APPROVAL

DISTRICT RAZOR USE SFD

#BEDROOMS 3


Date 4-17-01 J. Messinger
Zoning Administrator

Carroll J. Horner
D.B. 1326, Pg. 21
PIN 0506


Required Property Line Setbacks

	Minimum	Actual
Front	35	100
Side	10	25
Corner	20	-
Rear	25	180+
Nearest Building	10	-

Chain Link fence along property



5' deep
4' high
shallow
run to
30'



run
run back
to 18" run
run back
to 30' R

Must meet
on site if plus
is not stub
out where
shown