

# SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER


APPLICANT NAME \_\_\_\_\_

DATE \_\_\_\_\_

FACTORS		PROFILES													
		1	2	3	4	5	6	7	8	9	10				
LANDSCAPE POSITION	.1940	L													
SLOPE (%)	.1940	2.5													
HORIZON 1 DEPTH		0-32"	0-24"	0-34"	0-30"										
Texture Group	.1941(A)(1)	SL	SL	SL	SL/LS										
Consistence	.1941	VFR	VFR	VFR	VFR										
Structure	.1941(A)(2)	G	G	G	G										
Mineralogy	.1941(A)(3)	SEXP	SEXP	SEXP	SEXP										
HORIZON 2 DEPTH		32"	24"	34"											
Texture Group	.1941(A)(1)	SCL	SCL	SCL											
Consistence	.1941	FR	FR	FR											
Structure	.1941(A)(2)	SBX	SBK	G/SBK											
Mineralogy	.1941(A)(3)	SEXP	SEXP	SEXP											
HORIZON 3 DEPTH															
Texture Group	.1941(A)(1)														
Consistence	.1941														
Structure	.1941(A)(2)														
Mineralogy	.1941(A)(3)														
HORIZON 4 DEPTH															
Texture Group	.1941(A)(1)														
Consistence	.1941														
Structure	.1941(A)(2)														
Mineralogy	.1941(A)(3)														
SOIL WETNESS	.1942														
RESTRICTIVE HORIZON	.1944														
SAPROLITE	.1943/1956														
CLASSIFICATION	.1948	PS	PS	PS	PS										
LONG TERM ACCEPTANCE RATE	.1955	.8	.4	.5	.8										

FRONT PROPERTY LINE (NOT ROAD)

ROAD



4 75' LINES  
18" DEEP  
PUMP TO CONV.  
RUN LINES ON CENTER  
9' ON CENTER

① CONV. REPAIR

④