## **OPERATIONS PERMIT**

	$\wedge$	01-5-1864
Name: (owner) Property Location:	DANNY MORRIS  SR#_ 1115  Subdivision CRESTURY	New Installation  Septic Tank  Repairs  Nitrification Lin  Lot #
Contractor:	BROWN	Quadrant #
Basement with Plum		
	Well Public Community	
Following are the specifications for the sewage disposal system on above captioned property.		
Type of system:	Conventional Other	
Size of tank:	Septic Tank: / gallons Pu	ımp Tank: gallons
Subsurface Drainage Field	No. of ditches exact length of each ditch 200 f	width of depth of depth of ditches 18-24 in.
French Drain:	Linear feet  Date:	8-23-01
PERMIT NO.	232 Inspected	by: Environmental Health Specialist
	The state of the s	11 25'