

SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER


APPLICANT NAME _____

DATE 6/29/01

FACTORS		PROFILES									
		1	2	3	4	5	6	7	8	9	10
LANDSCAPE POSITION	.1940	LS	LS	LS	LS	LS					
SLOPE (%)	.1940	5-7	5-7	5-7	5-7	5-7					
HORIZON 1 DEPTH		0-34	0-24	0-24	0-34	0-40					
Texture Group	.1941(A)(1)	LS	LS	LS	LS	LS					
Consistence	.1941	VFR	VFR	VFR	VFR	VFR					
Structure	.1941(A)(2)	G	G	G	G	G					
Mineralogy	.1941(A)(3)	NS/MP	NS/MP	NS/MP	NS/MP	NS/MP					
HORIZON 2 DEPTH		34"	24"	24"	34"	40"					
Texture Group	.1941(A)(1)	SCL	SCL	SCL	SCL	SCL					
Consistence	.1941	FR	FR	FR	FR	FR					
Structure	.1941(A)(2)	SBK/G	SBK	SBK	SBK	SBK					
Mineralogy	.1941(A)(3)	SS/SP	SS/SP	SS/SP	SS/SP	SS/SP					
HORIZON 3 DEPTH											
Texture Group	.1941(A)(1)										
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
HORIZON 4 DEPTH											
Texture Group	.1941(A)(1)										
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
SOIL WETNESS	.1942										
RESTRICTIVE HORIZON	.1944										
SAPROLITE	.1943/1956										
CLASSIFICATION	.1948	PS	PS	PS	PS	PS					
LONG TERM ACCEPTANCE RATE	.1955	.5	.5	.5	.5	.5					

3 80' LINES
ON CONTOUR
20-24" DEEP

#3 - APPROACHING PHY. WET @
36"



W0705