

# SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

APPLICANT NAME \_\_\_\_\_

DATE \_\_\_\_\_

FACTORS		PROFILES									
		1	2	3	4	5	6	7	8	9	10
LANDSCAPE POSITION	.1940	L	L	L	L						
SLOPE (%)	.1940	2	2	2	2						
HORIZON 1 DEPTH		0-30	0-48	0-48	0-30						
Texture Group	.1941(A)(1)	SL	SL	SL	SL						
Consistence	.1941	FK	PK	PK	PK						
Structure	.1941(A)(2)	CL	CL	CL	CL						
Mineralogy	.1941(A)(3)	NSNP	NSNP	NSNP	NSNP						
HORIZON 2 DEPTH		30-36			30-36						
Texture Group	.1941(A)(1)	SL			SL						
Consistence	.1941	PK			PK						
Structure	.1941(A)(2)	CL			CL						
Mineralogy	.1941(A)(3)	SSP			SSP						
HORIZON 3 DEPTH		36-48			36-48						
Texture Group	.1941(A)(1)	SL CL			SL CL						
Consistence	.1941	PK			PK						
Structure	.1941(A)(2)	PK			PK						
Mineralogy	.1941(A)(3)	SSP			SSP						
HORIZON 4 DEPTH											
Texture Group	.1941(A)(1)										
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
SOIL WETNESS	.1942										
RESTRICTIVE HORIZON	.1944										
SAPROLITE	.1943/1956										
CLASSIFICATION	.1948										
LONG TERM ACCEPTANCE RATE	.1955	.4	.7	.7	.4						