

SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

APPLICANT NAME _____

DATE _____

| FACTORS | | PROFILES | | | | | | | | | | | | | |
|---------------------------|-------------|----------|------|------|---|---|---|---|---|---|----|--|--|--|--|
| | | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | | | | |
| LANDSCAPE POSITION | .1940 | | | | | | | | | | | | | | |
| SLOPE (%) | .1940 | | | | | | | | | | | | | | |
| HORIZON 1 DEPTH | | 0-3 | 0-5 | 0-36 | | | | | | | | | | | |
| Texture Group | .1941(A)(1) | SL | SL | C | | | | | | | | | | | |
| Consistence | .1941 | VR | VR | F. | | | | | | | | | | | |
| Structure | .1941(A)(2) | G | G | SBK | | | | | | | | | | | |
| Mineralogy | .1941(A)(3) | NOX | NOX | SOX | | | | | | | | | | | |
| HORIZON 2 DEPTH | | 3-36 | 5-36 | | | | | | | | | | | | |
| Texture Group | .1941(A)(1) | C | C | | | | | | | | | | | | |
| Consistence | .1941 | F. | F. | | | | | | | | | | | | |
| Structure | .1941(A)(2) | SBK | SBK | | | | | | | | | | | | |
| Mineralogy | .1941(A)(3) | SOX | SOX | | | | | | | | | | | | |
| HORIZON 3 DEPTH | | | | | | | | | | | | | | | |
| Texture Group | .1941(A)(1) | | | | | | | | | | | | | | |
| Consistence | .1941 | | | | | | | | | | | | | | |
| Structure | .1941(A)(2) | | | | | | | | | | | | | | |
| Mineralogy | .1941(A)(3) | | | | | | | | | | | | | | |
| HORIZON 4 DEPTH | | | | | | | | | | | | | | | |
| Texture Group | .1941(A)(1) | | | | | | | | | | | | | | |
| Consistence | .1941 | | | | | | | | | | | | | | |
| Structure | .1941(A)(2) | | | | | | | | | | | | | | |
| Mineralogy | .1941(A)(3) | | | | | | | | | | | | | | |
| SOIL WETNESS | .1942 | | | | | | | | | | | | | | |
| RESTRICTIVE HORIZON | .1944 | | | | | | | | | | | | | | |
| SAPROLITE | .1943/1956 | | | | | | | | | | | | | | |
| CLASSIFICATION | .1948 | PS | PS | PS | | | | | | | | | | | |
| LONG TERM ACCEPTANCE RATE | .1955 | .3 | .3 | .3 | | | | | | | | | | | |

