

SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

APPLICANT NAME _____

DATE _____

FACTORS		PROFILES									
		1	2	3	4	5	6	7	8	9	10
LANDSCAPE POSITION	.1940										
SLOPE (%)	.1940										
HORIZON 1 DEPTH		0-14	0-16	0-20							
Texture Group	.1941(A)(1)	LS	LS	LS							
Consistence	.1941	VF	VF	VF							
Structure	.1941(A)(2)	G	G	G							
Mineralogy	.1941(A)(3)	Noy	Noy	Noy							
HORIZON 2 DEPTH		14-30	14-30	20-30							
Texture Group	.1941(A)(1)	SC	SC	SC							
Consistence	.1941	F	F	F							
Structure	.1941(A)(2)	SBL	SBL	SBL							
Mineralogy	.1941(A)(3)	SOP	SOP	SOP							
HORIZON 3 DEPTH											
Texture Group	.1941(A)(1)										
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
HORIZON 4 DEPTH											
Texture Group	.1941(A)(1)										
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
SOIL WETNESS	.1942										
RESTRICTIVE HORIZON	.1944										
SAPROLITE	.1943/.1956										
CLASSIFICATION	.1948	PS	PS	PS							
LONG TERM ACCEPTANCE RATE	.1955	.4	.4	.4							

3
 2
 0

 Pa.

SITE PLAN APPROVAL

DISTRICT RA-30 USE SFD

#BEDROOMS 3

Date 26 Jun 01 [Signature]
 Zoning Administrator


Required Property Line Setbacks

	Required	Actual
Front	<u>35</u>	<u>30'</u>
Side	<u>10</u>	<u>17'</u>
Corner	<u>20</u>	<u>N/A</u>
Rear	<u>25</u>	<u>16.2'</u>
Nearest Building	<u>10</u>	<u>N/A</u>


Robert Jones General Contractor, Inc.
 Donnbrook Pines Lot 19

1" = 50'

4x75
 18px



Donnbrook Run



220