

HTE REPAIR

OPERATIONS PERMIT

Name: (owner) DALE B. HARRIS New Installation Septic Tank
 Property Location: SR# 1703 RED HILL CH. RD Repairs Nitrification Line
 Subdivision VILLAGE @ HUNTINGTON Lot # 1112
 Tax ID # _____ Quadrant # _____
 Contractor: JAMES BAREFOOT Registration # _____

Basement with Plumbing: Garage:

Water Supply: Well Public Community

Distance From Well: 50 ft.

Following are the specifications for the sewage disposal system on above captioned property.

Type of system: Conventional Other INFILTRATOR (QUICK 4)

Size of tank: Septic Tank: EXIST gallons Pump Tank: EXIST gallons

Subsurface	No. of	exact length	width of	depth of
Drainage Field	ditches <u>4</u>	of each ditch <u>100</u> ft.	ditches <u>3</u> ft.	ditches <u>18</u> in.

French Drain Required: _____ Linear feet

Date: 2/23/05
 Inspected by: [Signature] RS
 Environmental Health Specialist

PERMIT NO. 21297

