


# SITE/ L EVALUATION FOR ON-S WASTEWATER

APPLICANT NAME \_\_\_\_\_

DATE \_\_\_\_\_

FACTORS		PROFILES									
		1	2	3	4	5	6	7	8	9	10
LANDSCAPE POSITION	.1940										
SLOPE (%)	.1940										
HORIZON 1 DEPTH							0-30"	0-30"	0-18"		
Texture Group	.1941(A)(1)						LS/L	LS/L	S2/L3		
Consistence	.1941						VFR	VFR	VFR		
Structure	.1941(A)(2)						G	C	G		
Mineralogy	.1941(A)(3)						NS/MP	NS/MP	NS/MP		
HORIZON 2 DEPTH							30-36"	30-38"	18'-38"		
Texture Group	.1941(A)(1)						SCL	SCL	C		
Consistence	.1941						FR	FR	F1		
Structure	.1941(A)(2)						SBK/G	SBK/C	SBK		
Mineralogy	.1941(A)(3)						SS/SP	SS/SP	S/P		
HORIZON 3 DEPTH							26"±	38"±	33"±		
Texture Group	.1941(A)(1)						C/PM <sup>25%</sup>	C	C/PM		
Consistence	.1941						FR/F1	F1	F1		
Structure	.1941(A)(2)						SBK/G	SBK	SBK		
Mineralogy	.1941(A)(3)						S/P	S/P	S/P		
HORIZON 4 DEPTH											
Texture Group	.1941(A)(1)										
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
SOIL WETNESS	.1942										
RESTRICTIVE HORIZON	.1944										
SAPROLITE	.1943/.1956										
CLASSIFICATION	.1948						P3	P3	P3		
LONG TERM ACCEPTANCE RATE	.1955						.4	.4	.4		

↑ PM @ 36"



LPP  
FILL

3 80'  
25% REO  
18-20" DEEP



