

SITE/SI EVALUATION FOR ON-SI WASTEWATER

APPLICANT NAME _____

DATE _____

FACTORS		PROFILES												
		1	2	3	4	5	6	7	8	9	10			
LANDSCAPE POSITION	.1940													
SLOPE (%)	.1940													
HORIZON 1 DEPTH		2.48												
Texture Group	.1941(A)(1)	SL												
Consistence	.1941													
Structure	.1941(A)(2)													
Mineralogy	.1941(A)(3)													
HORIZON 2 DEPTH														
Texture Group	.1941(A)(1)													
Consistence	.1941													
Structure	.1941(A)(2)													
Mineralogy	.1941(A)(3)													
HORIZON 3 DEPTH														
Texture Group	.1941(A)(1)													
Consistence	.1941													
Structure	.1941(A)(2)													
Mineralogy	.1941(A)(3)													
HORIZON 4 DEPTH														
Texture Group	.1941(A)(1)													
Consistence	.1941													
Structure	.1941(A)(2)													
Mineralogy	.1941(A)(3)													
SOIL WETNESS	.1942													
RESTRICTIVE HORIZON	.1944													
SAPROLITE	.1943/.1956													
CLASSIFICATION	.1948													
LONG TERM ACCEPTANCE RATE	.1955	.6												

14200
18.24


PINE VALLEY
 50' R/W

(29)

PHASE - 1
 N 09°23'38"W

(48)

0.344
 AC.



SITE PLAN APPROVAL
 DISTRICT RA-20R USE 5FD
 #BEDROOMS 3
 18 Set P
 Zoning Administrator
 Date

Required Property Line Setbacks

Minimum	Actual
35	50
10	22
20	17
25	50
10	17

#47 Crestview
 Cumberland Homes

Southeastern Soil & Environmental Associates, Inc.

Soil - Environmental Consultant

P.O. Box 9321 • Fayetteville, NC 28311


Phone/Fax: (910) 822-4540

P.O. Box 808 • Fuquay-Varina, NC 27526

Phone/Fax: (919) 567-3017

4700

75
+55
130



Ernestine
Ryann
Area

1 x 200
18.24

ROAD CUT & TAPERED

TYPSOIL

- 0-20 LB
- 20-36" SCAM
- 0.6 LTAR
- (PUMP TO) 3x70' CONV.

DANNY

NOTE: WITH THE ROAD CUT, THE SYSTEM WOULD HAVE TO BE PUMPED TO BACK. IF THE HOUSE IS PUSHED BACK TO 75 FEET THEN YOU COULD GET GRAVITY FLOW TO FRONT.