


SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

APPLICANT NAME _____

DATE _____

| FACTORS | | PROFILES | | | | | | | | | | | | | |
|---------------------------|-------------|----------|-------|-------|------|---|---|---|---|---|----|--|--|--|--|
| | | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | | | | |
| LANDSCAPE POSITION | .1940 | | | | | | | | | | | | | | |
| SLOPE (%) | .1940 | | | | | | | | | | | | | | |
| HORIZON 1 DEPTH | | 0-10 | 0-10 | 0-20 | 0-8 | | | | | | | | | | |
| Texture Group | .1941(A)(1) | SH | SH | SH | SH | | | | | | | | | | |
| Consistence | .1941 | VF | VF | VF | VF | | | | | | | | | | |
| Structure | .1941(A)(2) | G | G | G | G | | | | | | | | | | |
| Mineralogy | .1941(A)(3) | NOV | NOV | NOV | NOV | | | | | | | | | | |
| HORIZON 2 DEPTH | | 10-30 | 10-30 | 20-30 | 8-30 | | | | | | | | | | |
| Texture Group | .1941(A)(1) | SC1 | SC1 | SC1 | SC1 | | | | | | | | | | |
| Consistence | .1941 | F | F | F | F | | | | | | | | | | |
| Structure | .1941(A)(2) | SB | SB | SB | SB | | | | | | | | | | |
| Mineralogy | .1941(A)(3) | SO | SO | SO | SO | | | | | | | | | | |
| HORIZON 3 DEPTH | | | | | | | | | | | | | | | |
| Texture Group | .1941(A)(1) | | | | | | | | | | | | | | |
| Consistence | .1941 | | | | | | | | | | | | | | |
| Structure | .1941(A)(2) | | | | | | | | | | | | | | |
| Mineralogy | .1941(A)(3) | | | | | | | | | | | | | | |
| HORIZON 4 DEPTH | | | | | | | | | | | | | | | |
| Texture Group | .1941(A)(1) | | | | | | | | | | | | | | |
| Consistence | .1941 | | | | | | | | | | | | | | |
| Structure | .1941(A)(2) | | | | | | | | | | | | | | |
| Mineralogy | .1941(A)(3) | | | | | | | | | | | | | | |
| SOIL WETNESS | .1942 | 26" | 36" | | | | | | | | | | | | |
| RESTRICTIVE HORIZON | .1944 | | | | | | | | | | | | | | |
| SAPROLITE | .1943/.1956 | | | | | | | | | | | | | | |
| CLASSIFICATION | .1948 | US1B | PS | PS | PS | | | | | | | | | | |
| LONG TERM ACCEPTANCE RATE | .1955 | .4 | .4 | .4 | .3 | | | | | | | | | | |



④