

SITE/S EVALUATION FOR ON-S WASTEWATER

APPLICANT NAME _____

DATE _____

| FACTORS | | PROFILES | | | | | | | | | |
|---------------------------|-------------|----------|-------|-------|---|---|---|---|---|---|----|
| | | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
| LANDSCAPE POSITION | .1940 | L | L | L | | | | | | | |
| SLOPE (%) | .1940 | Z | ~ | Z | | | | | | | |
| HORIZON 1 DEPTH | | 0-12 | 0-12 | 0-12 | | | | | | | |
| Texture Group | .1941(A)(1) | SL | SL | SL | | | | | | | |
| Consistence | .1941 | FN | FN | FN | | | | | | | |
| Structure | .1941(A)(2) | GN | GN | GN | | | | | | | |
| Mineralogy | .1941(A)(3) | NSNP | NSNP | NSNP | | | | | | | |
| HORIZON 2 DEPTH | | 12-18 | 12-18 | 12-18 | | | | | | | |
| Texture Group | .1941(A)(1) | SCL | SCL | SCL | | | | | | | |
| Consistence | .1941 | FN | FN | FN | | | | | | | |
| Structure | .1941(A)(2) | GN | GN | GN | | | | | | | |
| Mineralogy | .1941(A)(3) | SSP | SSP | SSP | | | | | | | |
| HORIZON 3 DEPTH | | 18-24 | 18-24 | 18-24 | | | | | | | |
| Texture Group | .1941(A)(1) | CL | CL | CL | | | | | | | |
| Consistence | .1941 | FN | FN | FN | | | | | | | |
| Structure | .1941(A)(2) | GN | GN | GN | | | | | | | |
| Mineralogy | .1941(A)(3) | SSP | SSP | SSP | | | | | | | |
| HORIZON 4 DEPTH | | | | | | | | | | | |
| Texture Group | .1941(A)(1) | | | | | | | | | | |
| Consistence | .1941 | | | | | | | | | | |
| Structure | .1941(A)(2) | | | | | | | | | | |
| Mineralogy | .1941(A)(3) | | | | | | | | | | |
| SOIL WETNESS | .1942 | 32 | 34 | 20 | | | | | | | |
| RESTRICTIVE HORIZON | .1944 | | | | | | | | | | |
| SAPROLITE | .1943/1956 | | | | | | | | | | |
| CLASSIFICATION | .1948 | | | | | | | | | | |
| LONG TERM ACCEPTANCE RATE | .1955 | .35 | .35 | - | | | | | | | |

