

SITE/S . EVALUATION FOR ON-S WASTEWATER

APPLICANT NAME _____

DATE _____

FACTORS		PROFILES												
		1	2	3	4	5	6	7	8	9	10			
LANDSCAPE POSITION	.1940													
SLOPE (%)	.1940													
HORIZON 1 DEPTH		18-0	24-0	12-6	24-0	8-0	12-0	24-0	24-0					
Texture Group	.1941(A)(1)	F.II	F.II	F.II	F.II	F.II	F.II	F.II	F.II					
Consistence	.1941													
Structure	.1941(A)(2)													
Mineralogy	.1941(A)(3)													
HORIZON 2 DEPTH		0-42	0-42	0-42	0-42	0-38	0-42	0-36	0-36					
Texture Group	.1941(A)(1)	SCL	SCL	SCL	SCL	SCL	SCL	SCL	SCL					
Consistence	.1941													
Structure	.1941(A)(2)													
Mineralogy	.1941(A)(3)													
HORIZON 3 DEPTH						38+		36+	36+					
Texture Group	.1941(A)(1)					SEm		SEm	SEm					
Consistence	.1941													
Structure	.1941(A)(2)													
Mineralogy	.1941(A)(3)													
HORIZON 4 DEPTH														
Texture Group	.1941(A)(1)													
Consistence	.1941													
Structure	.1941(A)(2)													
Mineralogy	.1941(A)(3)													
SOIL WETNESS	.1942													
RESTRICTIVE HORIZON	.1944													
SAPROLITE	.1943/1956													
CLASSIFICATION	.1948													
LONG TERM ACCEPTANCE RATE	.1955	.6	.6	.6	.6	.5	.6	.5	.5					