## OPERATIONS PERMIT 01-5-2993

Name: (owner)	New Installation Septic Tank  SR# New Installation Septic Tank  Repairs Nitrification Lin  Subdivision Frach Tau  Lot # 165
Property Location:	SR# Nitrification Lin
	Subdivision Prach Tau Lot # 165
	TAX ID# Quadrant #
Contractor:	Blown Registration #
Basement with Plum	
Water Supply:	Well Public Community
Distance From Well:	Well Public Community  ft.
Following are the sp	pecifications for the sewage disposal system on above captioned property.
Type of system:	Conventional Other
Size of tank:	Septic Tank: gallons Pump Tank: gallons
Subsurface Drainage Field	No. of ditches exact length width of depth of of each ditches ft. ditches ft. ditches in.
French Drain:	Linear feet
1.0	Date: 0 -  8-02
PERMIT NO	Date: 01-18-02 Inspected by: Environmental Health Specialist
	115 10
	Repair And