Department of Environment, Health and Nat...... Resources
Division of Environmental Health
On-Site Wastewater Section

Sheet: Property ID: Lot #: File #: Code:

## SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Location Water Evalua		Auge	Date Desi Prop	☐ Pit	Property S  Well Spring	Ot	her		8
P R O F I L E	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
	V6-87,	C-72	a/15	Strusse Frsss	7				4
		72-42	soll(scl	F-SISA					85.6
							9		
					2				
					***************************************				

Description	Initial System	Repair System	Other Factors (.1946): Site Classification (.1948):
	System		Site Classification (.1946):72
Available Space (. 1945)			Evaluated By: 🔑
System Type(s)		25%.	Others Present:
Site LTAR		. 6	