

# SITE/S . EVALUATION FOR ON-SI WASTEWATER

APPLICANT NAME \_\_\_\_\_

DATE \_\_\_\_\_

FACTORS		PROFILES									
		1	2	3	4	5	6	7	8	9	10
LANDSCAPE POSITION	.1940										
SLOPE (%)	.1940										
HORIZON 1 DEPTH		0-26									
Texture Group	.1941(A)(1)	SAP									
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
HORIZON 2 DEPTH											
Texture Group	.1941(A)(1)										
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
HORIZON 3 DEPTH											
Texture Group	.1941(A)(1)										
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
HORIZON 4 DEPTH											
Texture Group	.1941(A)(1)										
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
SOIL WETNESS	.1942										
RESTRICTIVE HORIZON	.1944										
SAPROLITE	.1943/.1956	0-26									
CLASSIFICATION	.1948	U									
LONG TERM ACCEPTANCE RATE	.1955										

PIT 3 100% SAP @ 19"  
TEXTURE = LS

PIT 4 SAMPLE FROM 24" SIL/SICL  
ABOVE 24"  
NEAR STRUCTURE  
SIL

PIT 1 SIL/SICL

PIT 2 SIL/SICL

.5

1 X 10

