

SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

APPLICANT NAME _____

DATE _____

FACTORS		PROFILES									
		1	2	3	4	5	6	7	8	9	10
LANDSCAPE POSITION	.1940	L	L	L	L						
SLOPE (%)	.1940	Z	Z	Z	Z						
HORIZON 1 DEPTH		6-18	0-18	0-18	0-30						
Texture Group	.1941(A)(1)	SL	SL	SL	SL						
Consistence	.1941	PK	PK	PK	PK						
Structure	.1941(A)(2)	GM	GM	GM	GM						
Mineralogy	.1941(A)(3)	NSNP	NSNP	NSNP	NSNP						
HORIZON 2 DEPTH		18-24	18-24	18-24							
Texture Group	.1941(A)(1)	SL	SL	SL							
Consistence	.1941	PK	PK	PK							
Structure	.1941(A)(2)	GM	GM	GM							
Mineralogy	.1941(A)(3)	SSSP	SSSP	SSSP							
HORIZON 3 DEPTH		24-36	24-36	24-36							
Texture Group	.1941(A)(1)	SC-CL	SC-CL	SC-CL							
Consistence	.1941	PK	PK	PK							
Structure	.1941(A)(2)	GM	GM	GM							
Mineralogy	.1941(A)(3)	SSSP	SSSP	SSSP							
HORIZON 4 DEPTH											
Texture Group	.1941(A)(1)										
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
SOIL WETNESS	.1942	32	30	24	—						
RESTRICTIVE HORIZON	.1944										
SAPROLITE	.1943/.1956				U						
CLASSIFICATION	.1948										
LONG TERM ACCEPTANCE RATE	.1955	.34	.34	.35	—						

0r 180



MAP NORTH

Map # 2000-350



VICINITY MAP

Survey For

5

NOT A SURVEY
Proposed House
Location Only

Grove Twp.	Harnett Co.
Scale: 1" = 60'	Date: 10-24-2001

Surveyed & Mapped By

STREAMLINE

LAND SURVEYING, Inc.

870 N.C. Hwy. 55 West, Coats, N.C. 27521
910-897-7715 910-897-7284 (FAX)

heretofore certify that the survey represented herein was actually made upon the ground and is correct; and that there were no encroachments either way across property lines except as shown.



NOT FOR RECORDATION

2

ကဏ္ဍခွဲစာအုပ်