

SITE/S . EVALUATION FOR ON-SI WASTEWATER


APPLICANT NAME _____

DATE _____

FACTORS		PROFILES													
		1	2	3	4	5	6	7	8	9	10				
LANDSCAPE POSITION	.1940														
SLOPE (%)	.1940														
HORIZON 1 DEPTH		30													
Texture Group	.1941(A)(1)	Stc													
Consistence	.1941														
Structure	.1941(A)(2)														
Mineralogy	.1941(A)(3)														
HORIZON 2 DEPTH		36													
Texture Group	.1941(A)(1)	Soil/100 wt													
Consistence	.1941														
Structure	.1941(A)(2)														
Mineralogy	.1941(A)(3)														
HORIZON 3 DEPTH															
Texture Group	.1941(A)(1)														
Consistence	.1941														
Structure	.1941(A)(2)														
Mineralogy	.1941(A)(3)														
HORIZON 4 DEPTH															
Texture Group	.1941(A)(1)														
Consistence	.1941														
Structure	.1941(A)(2)														
Mineralogy	.1941(A)(3)														
SOIL WETNESS	.1942														
RESTRICTIVE HORIZON	.1944														
SAPROLITE	.1943/.1956														
CLASSIFICATION	.1948														
LONG TERM ACCEPTANCE RATE	.1955	2													

6 x 100

18" max
Prop to front



SITE PLAN APPROVAL

DISTRICT R-10 USE SPD

#BEDROOMS 1+/- AC 3

Date 10-31-09 [Signature]
Zoning Administrator

Required Property Line Setbacks

	Minimum	Actual
Front	35	135
Side	20	130
Corner	25	100+
Rear	10	100+
Nearest Building		

2001.263

Mark
on h

60 x 100
18

Once
cleared for
fence

Shallow
walk
Good for
her

