


SITE/ L EVALUATION FOR ON-S WASTEWATER

APPLICANT NAME _____

DATE _____

FACTORS		PROFILES									
		1	2	3	4	5	6	7	8	9	10
LANDSCAPE POSITION	.1940										
SLOPE (%)	.1940										
HORIZON 1 DEPTH		0-6	Rock	Rock	Rock	0-10	0-6	0-4	0-2		
Texture Group	.1941(A)(1)	C				Sh	Sh	Sh	Sh		
Consistence	.1941	F:				Vh	Vh	Vh	Vh		
Structure	.1941(A)(2)	SBK				G	G	G	G		
Mineralogy	.1941(A)(3)	STX				WSEI	WSEY	WSEK	WSEM		
HORIZON 2 DEPTH		6+				10-26	0-26	4-26	2-26		
Texture Group	.1941(A)(1)	LoS				C	C	C	C		
Consistence	.1941					F:	F:	V:	F:		
Structure	.1941(A)(2)					ADK	ADK	ADK	ADK		
Mineralogy	.1941(A)(3)					SEW	SEW	SEW	SEW		
HORIZON 3 DEPTH											
Texture Group	.1941(A)(1)										
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
HORIZON 4 DEPTH											
Texture Group	.1941(A)(1)										
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
SOIL WETNESS	.1942										
RESTRICTIVE HORIZON	.1944										
SAPROLITE	.1943/.1956										
CLASSIFICATION	.1948					PS	PS	PS	PS		
LONG TERM ACCEPTANCE RATE	.1955					.3	.3	.7	.7		



L.d.

3 X 135
18-24"
on the
contour

